



U.S. Department of Transportation

National Highway Traffic Safety Administration

# Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

\*\*\* \*\*\* \*\*\*



Case Vehicle (A): 1999 Mercury Type: Mountaineer, 4-door SUV

Driver: 56-year-old male

CDC: 12-FZEW-2

Vehicle (B): 2000 Ford

Type: E-350 extended passenger van

Driver: 39-year-old female

CDC: 06-BYEW-2

# **SITUATION**

(Slide 1) Case vehicle (A) was traveling west in the outside westbound lane of a straight section of a dry, asphalt, four-lane roadway, (slide 2) with a speed limit of 64 kph (40 mph). Vehicle (B) was traveling west in the same westbound lane, ahead of case vehicle (A). The driver of case vehicle (A) reportedly took off his seatbelt to pick up an item that had fallen onto the floor from the right-front seat. When he looked up, he saw vehicle (B) stopping in traffic ahead of him. The driver of case vehicle (A) reportedly attempted to avoid a collision by veering to the left and braking. Case vehicle (A) struck the left rear of vehicle (B) with its right front.

# GENERAL VEHICLE DAMAGE AND ESTIMATED CRASH SEVERITIES

(Slide 3) Damage to case vehicle (A) was moderate. The direct-damage length was 100 cm and began at the right-front bumper corner, resulting in a 64% vehicle overlap. The maximum crush was 42 cm and occurred at the right-front bumper corner, above the bumper. The left wheelbase was extended 6 cm, and the right wheelbase was reduced 10 cm.

(Slide 4) Damage to vehicle (B) was minor. The direct-damage length was 100 cm and began at the left-rear bumper corner. The maximum crush to the bumper was 15 cm and occurred at the left-rear bumper corner. There was also damage to both halves of the rear cargo door above the bumper.

Using the WinSMASH accident-reconstruction program and (slides 5, 6, 7, 8, 9, 10, 11, 12, 13) c-values for case vehicle (A) and vehicle (B), the following impact severities were calculated:

		Calculated	Velocity Change	- kph (mph)
Vehicle	Variable	Total	Longitudinal	Latitudinal
Case Vehicle (A)	delta V	20 (12)	-20 (-12)	0 (0)
Vehicle (B)	delta V	17 (11)	17 (11)	0 (0)

# **DESCRIPTION OF DAMAGE TO CASE VEHICLE (A)**

## Exterior

(Slides 14, 15, 16, 17) The front bumper, the right headlight assembly, the grille, the radiator, the right fender, and the right-front wheel and strut were damaged. The hood was crushed, and the hood latch was jammed. Both hood hinges were damaged, but did not separate. The rear edge of the hood was not elevated, and did not contact the windshield. All doors remained closed and operational.

Interior

(Slides 18, 19, 20, 21, 22, 23) This vehicle was equipped with both steering-wheel and passenger frontal-impact airbags, which deployed during the frontal impact. No damage was noted to the airbag skins or (slides 24, 25, 26, 27) to the module doors/flaps. (Slide 28) The steering-wheel rim was not deformed and there was no deformation of the steering-wheel spokes. The left side of the sunroof molding, the left sunvisor, the windshield and the driver knee bolster below the steering column were damaged from driver contact. There was no rotation of the steering column. No intrusions were noted.

(Slides 29, 30, 31, 32) No contact points were noted on the left-roof siderail, the left upper Apillar, or the left-front door interior panel. No damage was noted to the upper and mid instrument panels.

# OCCUPANT INJURIES AND KINEMATICS

The 6-ft, 1-in, 210-lb, 56-year-old male driver (slide 33) was <u>not</u> wearing the available three-point belt, and the steering-wheel airbag deployed. (Slide 34) On impact, he moved forward and to the right into and over the airbag, and his head contacted the edge of the sunroof frame and left sunvisor. He sustained an abrasion to his forehead, probably from contact with the sunroof frame molding, (slide 35) as indicated by a hair deposit, or possibly from contact with the left sunvisor, (slides 36, 37) as indicated by a scuff mark on the exterior surface of the visor and the broken left sunvisor vanity mirror. He sustained an abrasion to the nose, probably from contact by the airbag. He sustained a comminuted fracture, and dislocation of the right acetabulum and a contusion to

the right knee, (slides 38, 39) from axial loading through the thigh due to knee contact with the knee bolster. (Slide 40) A spider web pattern was noted near the center of the windshield, but no injury was reported that could be associated with it.

The following table and (slide 41) attached drawing summarize the injuries sustained by the driver.

· ···

Occupant: Driver Restraints: 3-point belt <u>not</u> worn; airbag deployed

Age: 56 years Stature: 185 cm (6 ft, 1 in)

Gender: Male Mass: 96 kg (210 lb)


			Injury Source	
Injury Description	A.I.S.	Definite	Probable	Possible
Abrasion, forehead	1		Sunroof molding	Sunvisor
Abrasion, nose	1		Airbag	
Fracture, comminuted with dislocation, right posterior acetabulum	3	Knee bolster		
Contusion, right knee	1	Knee bolster		
			†	
Maximum A.I.S. Level	<u>3</u>			
Injury Severity Score	<u>10</u>			

Duplicate columns 1-8 Module G I Format 0 11 Format 0 11	2 12	GENERAL INFORMATION	GI-1
TIME DATE OF COLLISION	y y	ENVIRONMENTAL CONDITIONS  CONSTRUCTION ZONE  (0) NO (1) YES (9) UNKNOWN  ROAD ALIGNMENT VERTICAL PLANE  (1) LEVEL (2) CREST OF HILL (3) SLOPE (2%) (4) BOTTOM OF HILL (9) UNKNOWN  ROAD ALIGNMENT HORIZONTAL PLANE  (1) STRAIGHT (2) CURVE (3) T - SHAPED (4) Y - SHAPED (7) OTHER: (9) UNKNOWN	33 1 34
ENVIRONMENTAL CONDITIONS  LIMITED-ACCESS HIGHWAY  (0) NO  (1) YES (9) UNKNOWN  ROAD, TOTAL TRAFFIC LANES (FOR CASE VEHICLE)  (1) 1-LANE (2) 2-LANES (3) 3-LANES (4) 4 OR MORE LANES (5) DIVIDED, 4 OR MORE LANES (6) PARKING LOT/DRIVEWAY (7) OTHER: (9) UNKNOWN  INTERSECTING RD, TOTAL LANES CHOOSE FROM ABOVE LIST, OR (8) NOT APPLICABLE  TYPE OF ROAD SURFACE  (1) ASPHALT (2) CONCRETE (3) GRAVEL (4) MORE THAN ONE (CIRCLE EACH) (7) OTHER: (9) UNKNOWN  ROAD DEFECTS  (0) NO (1) YES (9) UNKNOWN	$\frac{28}{28}$ $\frac{1}{29}$ $\frac{2}{30}$ $\frac{1}{31}$	(10) DRY  (21) WATER - DAMP (22) WATER - WET (23) WATER - PUDDLED (29) WATER - AMOUNT UNKNOWN  (31) SNOW - LOOSE (32) SNOW - PACKED (39) SNOW - CONDITION UNKNOWN  (41) ICE (51) SLUSH (61) SPILLED GRAVEL (71) OTHER: (99) UNKNOWN  VISIBILITY LIMITATION (FOR CASE VEHICLE)  (0) NONE (1) CLOUDY/DARK (2) FOG (3) SMOKE (4) WINDSHIELD CONDITION (5) GLARE (6) RAIN (7) OTHER: (8) ICE/SNOW (9) UNKNOWN  VISIBILITY OBSTRUCTION (FOR CASE VEHICLE)  (0) NONE (1) BUILDING (2) SIGN (3) VEGETATION (E.G. BUSHES, SHRUBS) (4) TREE (5) HILL OR CURVE IN ROAD (6) VEHICLE IN TRANSPORT (7) OTHER: (8) PARKED VEHICLE	<u>J</u> <u>Ø</u> 35 37

		GENERAL INFORMATION GI-2
ENVIRONMENTAL CONDITIONS  SPEED LIMIT  (0) 5-45 km/h 5-25 mph (1) 46-55 30 (2) 56-60 35 (3) 61-70 40 (4) 71-79 45 (5) 80-85 50 (6) 86-90 55 (7) 91-105 60 (8) OVER 105 65 (9) UNKNOWN  PRECIPITATION	3 40	MECHANICAL MALFUNCTION  WAS THERE MENTION OF A MECHANICAL MALFUNCTION IN CASE VEHICLE  (0) NO (1) YES (2) YES, DID NOT CONTRIBUTE TO ACCIDENT (9) UNKNOWN
(0) NONE (1) RAIN (2) SNOW (3) HAIL (4) FREEZING RAIN/SLEET (7) OTHER: (9) UNKNOWN  RATE OF PRECIPITATION  (1) LIGHT/MIST (2) MODERATE (3) HEAVY (8) NOT APPLICABLE (9) UNKNOWN  TEMPERATURE  (0) BELOW -15° C BELOW 5° F (1) -15 TO -6	9 41	THE FOLLOWING SECTION SHOULD BE FILLED OUT IF A MECHANICAL MALFUNCTION IS RECOGNIZED OR SUSPECTED.  CIRCLE ITEMS INVOLVED. SUPPORT ANY ITEMS CIRCLED WITH COMMENTS.  BRAKE SYSTEM DRIVER CONTROLS EXHAUST SYSTEM POWER TRAIN STEERING SYSTEM FUEL SYSTEM SUSPENSION SYSTEM VISIBILITY ITEMS ELECTRICAL SYSTEM TIRES THROTTLE CONTROLS UNKNOWN OTHER:  COMMENTS:  COMMENTS:
(1) LIGHT (2) STRONG (3) GUSTY & STRONG (9) UNKNOWN  LIGHT CONDITIONS  (1) DAYLIGHT (2) DAWN (3) DUSK (4) DARK, LIGHTED (5) DARK, UNLIGHTED (6) DARK, UNKNOWN IF LIGHTED (9) UNKNOWN	44	

		GENERAL INFORMATION	GI-3
CRASH DETAILS  CASE VEHICLE AND OBJECT  (0) NO (1) YES (9) UNKNOWN  CASE VEHICLE ROLLOVER  (0) NO ROLLOVER (1) YES, FIRST EVENT (2) YES, SUBSEQUENT EVENT (3) YES, SEQUENCE UNKNOWN (9) UNKNOWN	<u>₹</u>	HIGHEST POLICE INJURY SEVERITY CODE IN CRASH (NOT JUST CASE VEHICLE)  (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (9) UNKNOWN	2 55
CASE VEHICLE RAN OFF ROADWAY (BEFORE FIRST IMPACT)  (0) NO (1) YES (9) UNKNOWN  MOVING CASE VEHICLE AND CONTACTED MOVING VEHICLE (0) NO	49	DRIVER ALCOHOL INVOLVEMENT (CASE VEHICLE)  (0) NONE (1) YES (9) UNKNOWN/NOT REPORTED/ NO DRIVER  DRIVER ALCOHOL BAC (CASE VEHICLE)  (80) NO TEST	<u>©</u> ≈
(1) YES (9) UNKNOWN  CASE VEHICLE AND CONTACTED STOPPED VEHICLE  (0) NO (1) YES (9) UNKNOWN	50	(90) CHEMICAL TESTS, NO RESULTS (95) AUTOPSY, NO RESULTS (99) UNKNOWN  WAS THERE MENTION OF DRIVER IMPAIRMENT FOR CASE VEHICLE?  (0) NO (1) YES (9) UNKNOWN	57 58 <u>————————————————————————————————————</u>
STOPPED CASE VEHICLE AND CONTACTED VEHICLE  (0) NO (1) YES (9) UNKNOWN  TOTAL NUMBER OF VEHICLES CONTACTED	52	LIST IMPAIRMENTS MENTION	  IED: 
OF VEHICLES CONTACTED BY CASE VEHICLE IN CRASH  (8) 8 OR MORE (9) UNKNOWN  ANY FIRE IN THIS CRASH (NOT JUST CASE VEHICLE)  (0) NO (1) YES (9) UNKNOWN	<u></u>	POST - CRASH DETAIL  MANNER CASE VEHICLE LEFT SCENE  (1) DRIVEN (2) TOWED DUE TO DAMAGE (3) TOWED, NOT DUE TO DAMAGE (4) TOWED, REASON UNKNOWN (9) UNKNOWN	3 8

ACCIDENT DESCRIPTION: Case vehicle (A) was traveling west in the CASE VEHICLE (A): 1999 Mercury Mountainear outside west bound lane of a 4-lane roadway. Vehicle (B) was OTHER VEHICLE (B): 2000 Forz) E-350 van traveling west in the same westbound lane, ahead of case THIRD VEHICLE (C): N/A vehicle (A). The driver of case vehicle (A) reportedly took off his seat belt to pick up an item that had Sollen onto the floor from the right front seat. When he looked up, he saw vehicle (B) stopping in traffic ahead of him. The driver of case vehicle (A) reportedly attempted to avoid a Collision by veening to the left and broking. Case vehicle (A) struck the left-rear portion of vehicle NORTH (B) with its right-front end.



Duplicate columns 1-8 Module O V Format 0 4 from the previous card.	OTHER VEHICLE OV-1
MAKE: Ford  MODEL: E-350 extended van	CARGO:
VIN 1 E B S S 3 1 L	$7YH \bigcirc Q \bigcirc Q \bigcirc Q$
MANUFAC/BODY CODE $\frac{1}{30}$ $\frac{1}{34}$ MAKE/MODEL CODE $\frac{1}{30}$ $\frac{3}{34}$	VEHICLE TYPE  PASSENGER VEHICLE (02) LARGE
MODEL YEAR $\frac{2}{39} \Phi \Phi \Phi_{42}$	(03) LIMOUSINE (17) PICKUP CAR (20) UNKNOWN PASSENGER VEHICLE BODY (24) SUB-MINI (25) MINI (26) SUB-COMPACT (27) COMPACT
VEHICLE MASS (kg) $Q Q Q Q Q Q$	(28) INTERMEDIATE (29) FULL
IF SEPARATE REPORT WAS MADE, GIVE VEHICLE NUMBER	MULTIPURPOSE PASSENGER VEHICLE (14) SMALL UTILITY (WHEELBASE LESS THAN 107*, E.G. JEEP, BRONCO) (15) LARGE UTILITY (WHEELBASE MORE THAN 107*,
NUMBER OF OCCUPANTS (ENTER 9'S IF UNKNOWN)  S1	E.G. PANEL TRUCK, SUBURBAN)  (16) PICKUP TRUCK WITH CANOPY/SHELL COVER  (17) PICKUP CAR WITH CANOPY/SHELL COVER  (21) MOTOR HOME  (22) PICKUP TRUCK WITH SLIDE-IN CAMPER  (23) PICKUP CAR WITH SLIDE-IN CAMPER
TRAVELING SPEED (km/h) $\frac{9}{7}$	(31) CHASSIS-MOUNTED CAMPER
(000) PARKED OR STOPPED (995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN  Slowing down in the start of the	TRUCK (11) VAN (12) PICKUP TRUCK (13) UNKNOWN LIGHT TRUCK (15) LARGE UTILITY (E.G. PANEL TRUCK SUBURBAN) (16) PICKUP TRUCK WITH CANOPY/SHELL COVER (22) PICKUP TRUCK WITH SLIDE-IN CAMPER (30) UNKNOWN TRUCK TYPE (31) CHASSIS-MOUNTED CAMPER (33) DELIVERY VAN (WALK-IN)
HIGHEST POLICE INJURY SEVERITY CODE FOR THIS VEHICLE  (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (8) UNOCCUPIED VEHICLE (NOT APPLICABLE) (9) UNKNOWN	(34) STRAIGHT TRUCK (35) TRUCK-TRACTOR (BOBTAIL) (36) CHASSIS-CAB (37) UNKNOWN HEAVY TRUCK (38) TRACTOR & SEMI-TRAILER (SEMI) (39) TRUCK (OR SEMI) & FULL TRAILER(S)  BUS (40) UNKNOWN BUS TYPE (41) SCHOOL BUS (42) INTERCITY BUS (BETWEEN CITIES) (43) TRANSIT BUS (INTRACITY) (44) STREETCAR (ON TRACKS) (68) TRAIN (CARS) (69) LOCOMOTIVE (ENGINE, SWITCHER) (99) UNKNOWN
	WHEELBASE (cm) (999) UNKNOWN  55 59 60

Module O V Format 0 2 9 10 11 12 OTHER VEHICLE

OV-2

# **ORIGINAL SPECIFICATIONS**

Wheelbase 351 cm

Front Overhang

 $\underline{\emptyset} \, \underline{7} \, \underline{6} \, \text{cm}$ 

**Curb Weight** 

Rear Overhang

Average Track Width  $\frac{1}{13}$   $\frac{3}{15}$ 

Undeformed End Width (UEW)

 $\frac{1}{28}$  8  $\frac{6}{30}$  cm

Overall Length

$$\frac{589}{16}$$
 cm

Engine Displacement

 $\frac{5}{31}$ .  $\frac{4}{32}$ 


Overall Width (OAW)  $\frac{2}{19}$   $\Phi$   $\frac{1}{21}$  cm

Engine: # of Cylinders

 $\underbrace{\cancel{S}}_{33}$   $\underbrace{\cancel{S}}_{34}$ 

## VEHICLE DAMAGE

MEASUREMENTS IN CENTIMETERS



# FRONTAL CRASH OVERLAP

Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A. Direct Damage Length (DDL)

 $\frac{9}{15}$   $\frac{9}{37}$  cm

Front-End Overlap (Percent) = DDL UFW

\_\_\_\_\_

79%

Vehicle Overlap (Percent) = DDL + 1/2 (OAW - UEW)
OAW

99 %

Duplicate columns 1-8 Module V D Format from the previous card.	0 4		VEHICLE DES	SCRIPTION	VD-1
MAKE: Mercury  MODEL: Mountaineer			CARGO: 136K		eights
VIN 4 M T Z US	5	P L)	X V O		
MANUFAC/BODY CODE $\int_{30} 22$	15	STOLE	N VEHICLE		
MAKE/MODEL CODE <u>9</u>	<u>52</u>	(0) N (1) Y (8) N			8
MODEL YEAR $\frac{1}{39}$ $\frac{9}{9}$	9		INKNOWN		
VEHICLE MASS (kg) Q Q 22 0	6	l	STRUCTURE		2
ODOMETER (km) (ENTER 9'S IF UNKNOWN) (ENTER 8'S IF ELECTRONIC)  49	18	(2) U (3) IN (4) B	ODY & FRAME NITIZED ITEGRAL-STUB FRAME ODY & PLATFORM FRAME	Ē	63
NUMBER OF OCCUPANTS (ENTER 9'S IF UNKNOWN)	56	(5) P. (7) O	E.G. VW BUG) ARTIALLY UNITIZED THER: NKNOWN	_	
TRAVELING SPEED (km/h) 9	$-\frac{5}{59}$	TDANIC	MICCION		
(995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN	المدسك ا	(0) N( (1) AU (2) M/	MISSION ONE JTOMATIC ANUAL NKNOWN		64
VEHICLE TYPE		LOCATION	ON OF TRANSMISSIO	ON.	
PASSENGER VEHICLE (11) 2-DOOR HARDTOP (NO UPPER B-PILLAR) (12) 2-DOOR SEDAN OR COUPE  - (ANY UPPER B-PILLAR)	$\frac{2}{60}$	SELECT (1) FL	OR LEVER OOR	211	3
(13) 4-DOOR HARDTOP (14) 4-DOOR SEDAN (15) STATION WAGON (16) CONVERTIBLE (18) OTHER PASS. VEH. : (19) PASSENGER VEHICLE, TYPE UNKNOWN		(3) CC (7) OT	DNSOLE DLUMN THER: JKNOWN		65
MULTIPURPOSE PASSENGER VEHICLE (21) SMALL UTILITY (E.G. JEEP, SCOUT, BRONCO) (22) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN)		STEERIN			
(23) VAN, SIZE UNKNOWN (24) VAN, SMALL (MINI) (25) VAN, LARGE (29) MPV, TYPE UNKNOWN (30) MOTOR HOME		(1) PO (2) MA (9) UN			66
TRUCK (31) PICKUP TRUCK, UNKNOWN (32) PICKUP TRUCK, SMALL (DOWNSIZED) (33) PICKUP TRUCK, LARGE		BRAKES (1) PO (2) MA	WER NUAL		67
(99) UNKNOWN	-	(9) UN	KNOWN		

		VEHICLE DESCRIPTION VD-2
TYPE OF BRAKES  (1) DRUM, ALL WHEELS (2) DISC, FRONT WHEELS (3) DISC, ALL WHEELS (9) UNKNOWN	2 68	WHEELBASE <i>(cm)</i> (999) Unknown
BRAKE ANTI-LOCK DEVICE  (0) NONE INSTALLED (1) TWO-WHEEL (2) FOUR-WHEEL (7) EQUIPPED, UNKNOWN WHEELS (9) UNKNOWN  AIR CONDITIONING IN VEHICLE  (0) NO (1) YES (8) NOT COLLECTED (9) UNKNOWN	<b>8</b> 70	PLASTIC ANTI-LACERATIVE INNER LAYER GLASS EQUIPPED  (0) NONE (1) WINDSHIELD (2) WINDSHIELD AND SIDE (7) OTHER (9) UNKNOWN
TYPE OF DRIVE  (1) REAR WHEEL (2) FRONT WHEEL (3) FOUR WHEEL (4) ALL WHEEL DRIVE (9) UNKNOWN  DUAL REAR WHEELS  (0) NO (1) YES (9) UNKNOWN  ORIGINAL TYPE OF RESTRAINT SYSTEM  (1) ACTIVE BELT (2) PASSIVE BELT (3) AIRBAG (4) KNEE BOLSTERS (7) OTHER:  (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	$\frac{1}{71}$ $\frac{0}{72}$	FIELD INVESTIGATOR INSTRUCTIONS:  1. INDICATE CRUSHED AREAS BY OUTLLINING NEW PERIMETER OF VEHICLE AND SHADING THE DAMAGED AREAS ON THE LARGE SKETCH ON PAGE VD-3.  USE AS MANY SKETCHES AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE.  2. ENTER THE DIMENSIONS ON THE SKETCH(ES) MEASURED TO THE POINT OF MAXIMUM PENETRATION BY THE OBJECT(S) CONTACTED. USE THE EXAMPLES BELOW AS A GUIDE.  3. ENTER THE THREE DIMENSIONS TO THE CENTER OF THE WHEELS (WHEELBASE, FRONT AND REAR OVERHANGS) ON BOTH SIDES OF THE CAR.  4. ADD OTHER DIMENSIONS AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE. EXAMPLES:
(0) NO (1) YES (9) UNKNOWN  TYPE OF ROOF  (0) NONE (1) SOLID (2) T-TOP CLOSED (3) T-TOP OPEN (4) SUN ROOF CLOSED (5) SUN ROOF OPEN (6) CONVERTIBLE CLOSED (7) CONVERTIBLE OPEN (8) OTHER: (9) UNKNOWN	<del>4</del> <del>75</del>	FRONT OR REAR  ROOF (REFERENCE TO TOP OF DOOR SILL OR WINDOW SILL)

Module V D Format 0 2

VEHICLE DESCRIPTION

VD-3

# **ORIGINAL SPECIFICATIONS**

Wheelbase

Front Overhang

$$\underbrace{\mathcal{Q}}_{2} \underbrace{\mathcal{S}}_{2} \underbrace{\mathcal{G}}_{2^{4}} \text{ cm}$$

Curb Weight

Rear Overhang

$$\int_{5}^{2} \int_{0}^{2} \int_{0}^{24} cm$$

Average Track Width

$$\frac{1}{13} \frac{4}{9} \frac{9}{15}$$
 cm

Undeformed End Width (UEW)

$$\frac{1}{28} \int \frac{\sqrt{27}}{50} \, cm$$

Overall Length

$$\frac{4}{16}$$
 8  $\frac{1}{18}$  cm


Engine Displacement

Overall Width (OAW)  $\frac{1}{100}$   $\frac{7}{100}$   $\frac{8}{100}$   $\frac{8}{100}$ 

Engine: # of Cylinders

# **VEHICLE DAMAGE**

#### **MEASUREMENTS IN CENTIMETERS**



# FRONTAL CRASH OVERLAP

Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A. Direct Damage Length (DDL)

$$\frac{1}{35} \stackrel{\bigcirc}{\triangle} \frac{\cancel{O}}{\cancel{37}} cm$$

Front-End Overlap (Percent) = DDL UEW

Vehicle Overlap (Percent) = DDL + 1/2 (OAW - UEW)

Duplicate columns 1-8 Module D A from the previous card. 9 10	Format 0 2 11 12	DAMAGE DA-1
PRIMARY	CASE VEHICLE PRIMARY CDC	CONTACTED VEHICLE ASSOCIATED CDC
EVENT NUMBER		999
IMPACT SPEED (km/h)	14 15 16	$\frac{1}{35} \frac{1}{36} \frac{1}{37}$
ESTIMATED BY	17 Above	38
CRUSH (cm)	042 bumper	$ \underbrace{\mathbf{Q}}_{39} \underbrace{1}_{40} \underbrace{\mathbf{S}}_{41} $
CDC #1	12 FZEW.2	<u>06.ΒΥΕω.2</u>
CDC #2	<u>98.0000.0</u>	98.0000.05 55
Duplicate columns 1-8 Module D A from the previous card. 9 10	N Format 0 3 11 12	
SECONDARY	CASE VEHICLE SECONDARY CDC	CONTACTED VEHICLE ASSOCIATED CDC
EVENT NUMBER	<b>8</b> 13	
IMPACT SPEED (km/h)	14 15 16	35 36 37
ESTIMATED BY	17	38
CRUSH (cm)	18 19 20	39 40 41
CDC #1	21	42 48
CDC #2	28 34	49
Codes		
EVENT NUMBER	IMPACT SPEED ESTIMATOR	CRUSH
(8) NOT APPLICABLE (9) UNKNOWN	E (1) INVESTIGATOR (2) DRIVER	(998) NOT APPLICABLE (NO VEHICLE/DAMAGE)
IMPACT SPEED	(3) POLICE (4) "CRASH" PROGRAM	(999) UNKNOWN
(998) NOT APPLICAE (999) UNKNOWN	(5) OTHER COMPUTER PROGRAM SPECIFY: (7) OTHER: (8) NOT APPLICABLE (NO VEHICLE/NO IMPACT)	CDC (9800000) NOT APPLICABLE (9900000) UNKNOWN

BEST AVAILABLE DAMAGE DA-2 Module D A Format 0 1 12 **Duplicate columns 1-8** from the previous card. MAXIMUM SHEET METAL CRUSH (cm) (999) UNKNOWN **FRONT** RIGHT SIDE REAR LEFT SIDE ROOF **OTHER** CHRONOLOGICAL SEQUENCE OF DAMAGE/INJURY PRODUCING CRASH EVENTS FOR CASE VEHICLE DO YOU KNOW THIS TABLE TO BE IN CHRONOLOGICAL ORDER? NOTE: IF CHRONOLOGICAL ORDER IS UNKNOWN, EVENT ORDER IS OPTIONAL. (0) NO (1) YES EVENT NUMBER IMPACT CONFIGURATION OBJECT/VEHICLE CONTACTED **IMPACT LOCATION** (1) ON ROADWAY (2) SHOULDER/MEDIAN/GORE FOR CODES, SEE TABLE FOR CODES, SEE TABLE ON PAGE DA-4. (3) ON ROADSIDE ON PAGE DA-3. (4) OUTSIDE ROADSIDE **RIGHT-OF-WAY** (5) OTHER (6) OFF ROADWAY, LOC. UNK. (9) UNKNOWN #1 #2 37 #3 42 #4 47 #5 52 56 #6 57

#7

62

#### **CODES FOR** IMPACT CONFIGURATION

#### FRONT OF CASE VEHICLE

- (11) AND FRONT OF CONTACTED VEHICLE
- (13) AND SIDE OF CONTACTED VEHICLE
- (14) AND REAR OF CONTACTED VEHICLE
- (16) ENDSWIPED BY CONTACTED VEHICLE
- (17) AND OBJECT
- (19) AND UNKNOWN OTHER VEHICLE CONFIGURATION

## **LEFT SIDE OF CASE VEHICLE**

- (21) AND FRONT OF CONTACTED VEHICLE (TYPE T)
- (22) AND FRONT OF CONTACTED VEHICLE (TYPE L)
- (23) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
- (24) AND REAR OF CONTACTED VEHICLE (TYPE T)
  (25) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (26) SIDESWIPED BY CONTACTED VEHICLE
- (27) AND OBJECT
- (29) AND UNKNOWN OTHER VEHICLE CONFIGURATION

#### **REAR OF CASE VEHICLE**

- (31) AND FRONT OF CONTACTED VEHICLE
- (33) AND SIDE OF CONTACTED VEHICLE
- (34) AND REAR OF CONTACTED VEHICLE
- (36) ENDSWIPED BY CONTACTED VEHICLE
- (37) AND OBJECT
- (39) AND UNKNOWN OTHER VEHICLE CONFIGURATION

## **RIGHT SIDE OF CASE VEHICLE**

- (41) AND FRONT OF CONTACTED VEHICLE (TYPE T)
- (42) AND FRONT OF CONTACTED VEHICLE (TYPE L)
- (43) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
- (44) AND REAR OF CONTACTED VEHICLE (TYPE T) (45) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (46) SIDESWIPED BY CONTACTED VEHICLE
- (47) AND OBJECT
- (49) AND <u>UNKNOWN</u> OTHER VEHICLE CONFIGURATION

#### **OTHER**

- (57) VEHICLE TO OBJECT
- (58) VEHICLE TO VEHICLE
- (59) VEHICLE TO VEHICLE, CONFIGURATION UNKNOWN

#### ROLLOVER

- (61) LESS THAN 360°
- (62) 360° OR MORE
- (69) DETAILS UNKNOWN

#### **UNKNOWN**

(99) IMPACT TYPE UNKNOWN

#### CODES FOR VEHICLE/OBJECT CONTACTED

#### VEHICLE/OBJECT GROUPS

- NO OBJECT
- (01) (39) PASSENGER VEHICLE & TRUCK
- (40) (69) OTHER VEHICLE
- (70) (76) PEDESTRIAN & ON-ROADWAY OBJECT
- (77) (97) OFF-ROADWAY OBJECT
- OTHER (DESCRIBE) (98)
- (99) UNKNOWN

#### PASSENGER VEHICLE

- (02) LARGE
- (03) LIMOUSINE
- (17) PICKUP
- (20) UNKNOWN PASSENGER VEHICLE BODY
- (24) SUB-MINI
- (25) MINI
- (26) SUB-COMPACT
- (27) COMPACT
- (28) INTERMEDIATE
- (29) FULL

#### SIZE

#### **WHEELBASE**

SUB-MINI < 2286 mm ( < 90") 2286 - 2412 mm (90" - 94.9") MINI 2413 - 2539 mm (95" - 99.9") SUB-COMPACT COMPACT 2540 - 2666 mm (100" - 104.9") INTERMEDIATE 2667 - 2793 mm (105" - 109.9") 2794 - 2920 mm (110" - 114.9") **FULL** LARGE 2921 - 3174 mm (115" - 124.9") > 3175 mm (> 125°) LIMOUSINE

# MULTIPURPOSE PASSENGER VEHICLE

- (11) SMALL VAN (MINI)
- (12) PICKUP
- (14) SMALL UTILITY (WHEELBASE LESS THAN 107". E.G. JEEP, BRONCO)
- (15) LARGE UTILITY (WHEELBASE MORE THAN 107", E.G. PANEL TRUCK, SUBURBAN)
- (16) PICKUP TRUCK WITH CANOPY/SHELL COVER
- (17) PICKUP CAR WITH CANOPY/SHELL COVER
- (21) MOTOR HOME
- (22) PICKUP TRUCK WITH SLIDE-IN CAMPER
- (23) PICKUP CAR WITH SLIDE-IN CAMPER
- (31) CHASSIS-MOUNTED CAMPER

#### **TRUCK**

- (11) SMALL VAN (E.G. ECONOLINE)
- (12) PICKUP TRUCK
- (13) UNKNOWN LIGHT TRUCK
- (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN)
- (16) PICKUP TRUCK WITH CANOPY/SHELL COVER
- (22) PICKUP TRUCK WITH SLIDE-IN CAMPER
- (30) UNKNOWN TRUCK TYPE
- (31) CHASSIS-MOUNTED CAMPER
- (33) DELIVERY VAN (WALK-IN) (34) STRAIGHT TRUCK
- (35) TRUCK-TRACTOR (BOBTAIL)
- (36) CHASSIS-CAB
- (37) UNKNOWN HEAVY TRUCK
- (38) TRACTOR & SEMI-TRAILER (SEMI)
- (39) TRUCK (OR SEMI) & FULL TRAILER(S)

#### BUS

- (40) UNKNOWN BUS TYPE
- (41) SCHOOL BUS
- (42) INTERCITY BUS (BETWEEN CITIES)
- (43) TRANSIT BUS (INTRACITY)
- (44) STREETCAR (ON TRACKS)

#### MOTORCYCLE

- (50) UNKNOWN MOTORCYCLE TYPE
- (51) 1 75 cc (52) 76 125 cc
- (53) 126 250 cc
- (54) 251 500 cc
- (55) 501 750 ∞
- (56) 751 cc +
- (57) 3-WHEELS (OR WITH SIDECAR)

#### SPECIAL PURPOSE VEHICLE

- (60) UNKNOWN/OTHER SPECIAL VEHICLE (DESCRIBE)
- (61) SNOWMOBILE
- (62) ATV (ALL TERRAIN VEHICLE) (63) AMPHIBIOUS VEHICLE
- (64) FARM VEHICLE
- (65) CONSTRUCTION VEHICLE
- (66) TRAILER, PRIVATE (CAMPER)
- (67) TRAILER, COMMERCIAL (CARGO) (68) TRAIN (CARS)
- (69) LOCOMOTIVE (ENGINE, SWITCHER)

# **OBJECT**

- (70) PEDESTRIAN
- (71) BICYCLIST, OTHER PEDALCYCLIST
- (72) PEDESTRIAN CONVEYANCE (E.G. PERSON RIDING ANIMAL, CART)
- (73) LARGE ANIMAL
- (74) FALLEN OBJECT (E.G. OBJECT DISLODGED FROM OTHER VEHICLE, FALLEN TREE, ROCKS)
- (75) ROCKS
- (76) CONSTRUCTION EQUIPMENT (EXCLUDING (65))
- (77) SIGN POST, UTILITY POLE, TREE
- (78) DITCH
- (79) EMBANKMENT, SNOWBANK, RR TRACKS RR X
- (80) GROUND (ROLLOVER ONLY)
- (81) CURB (DAMAGE PRODUCING IMPACTS ONLY)
- (82) CULVERT
- (83) FENCE
- (84) HYDRANT, SHORT POST, STUMP
- (85) SMALL POST/TREE, RURAL MAIL BOX, MILE MARKER, DELINEATOR
- (86) BUILDING
- (87) PIER, PILLAR, BRIDGE SUPPORT
- (88) ABUTMENT, RETAINING WALL
- (89) BRIDGE RAIL

- (90) GUARD RAIL, LEADING SECTION
  (91) GUARD RAIL, MIDDLE OR UNKNOWN
  (92) GUARD RAIL, TRAILING SECTION
  (93) GUARD POST (TIMBER, METAL, CONCRETE)
- (94) CABLE, FENCE BARRIER
- (95) CONCRETE BARRIER (MEDIAN)
- (96) IMPACT ATTENUATOR (97) BREAKAWAY FEATURES

Duplicate columns 1-8 Module C F from the previous card. 9 10	R Format 0 1 1 12		H RECONSTRUC OT ΔV	TION CR-1	
	CASE VEHICLE P	PRIMARY IMPACT	CASE VEHICLE SECONDARY IMPACT		
	CASE VEHICLE	CONTACTED VEHICLE	CASE VEHICLE	CONTACTED VEHICLE	
EVENT NUMBER	13		47		
ΔV (km/h) TOTAL	<b>Q \( \) \</b>	$ \underbrace{0}_{32} \underbrace{1}_{33} \underbrace{7}_{34} $	48 49 50	66 67 68	
LONGITUDINAL*	$\frac{1}{2} \overline{Q} \overline{Y} \overline{Q}$	$+$ $\bigcirc$ $\perp$ $\frac{7}{35}$	51 54	69 72	
LATERAL*  *NOTE: THESE ΔV COMPONENTS  MUST INCLUDE SIGN.  EXAMPLES: 10 km/h = ± 0 1 0  -7 km/h = ± 2 0 7	<u>+</u> <u>0</u> <u>0</u> <u>0</u> <u>0</u>	<b>→ ○ ○ ○ ○ ○ ○</b>	55 58	73 76	
ENERGY DISSIPATED BY CRUSH (ki)	<b>Q Q 5 Q 2 3 3 4 3 3 3 4 3 3 3 3 3 3 3 3 3 3</b>	0021	59 62	77 — 80	
RECONSTRUCTION	49961	20649			
(01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL  (21) RECONSTRUCTED, LOW CONFIDENCE LEVEL  (22) RECONSTRUCTED, MODERATE CONFIDENCE LEVEL  (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL  NOT RECONSTRUCTED BECAUSE  (02) INSUFFICIENT DATA  (03) EXCESSIVE UNDERRIDE/ OVERRIDE  (04) ROLLOVER (05) VAULTING (06) OTHER TRAVEL IN MORE THAN ONE PLANE  (07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT (10) OTHER:  (11) AT LEAST ONE VEHICLE BEYOND SCOPE (12) OTHER VEHICLE NOT INSPECTED	2 1 30		63 64		
MODE  (1) CDC ONLY (2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC (4) TRAJECTORY & CDC & DETAILED DAMAGE (5) NOT RECONSTRUCTED  COMPUTER PROGRAM SPECIFY:	<u>2</u>		<del></del>		

Duplicate columns 1-8 from the previous card.  Module C F	Format <u>0 2</u>		H RECONSTRUCTERS	TION CR-2
	CASE VEHICLE PRIMARY IMPACT		CASE VEHICLE SECONDARY IMPACT	
	CASE VEHICLE	CONTACTED VEHICLE	CASE VEHICLE	CONTACTED VEHICLE
EVENT NUMBER	13		47	
EBS (km/h) TOTAL	<b>Q 2 7</b> 15 16	$ \underbrace{0}_{32} \underbrace{3}_{33} \underbrace{3}_{34} $	48 49 50	66 67 68
LONGITUDINAL*	$\frac{-\Phi \lambda 7}{17}$	<u>+Φ[8</u> 35	51 54	69 72
LATERAL*	+ 0 0 <u>0</u>	<u>+</u> Q Q Q		73 - 76
NOTE: THESE EBS COMPONENTS MUST INCLUDE SIGN.				
EXAMPLES: $10 \text{ km/h} = \pm 0.1 \Omega$ -7 km/h = $\pm 0.0 Z$				
ENERGY DISSIPATED BY CRUSH (kj)	<u>0</u> <u>0</u> <u>5</u> <u>0</u>	<u>O</u> <u>O</u> <u>A</u> <u>O</u>	59 62	77 80
RECONSTRUCTION	49961	20015		
(01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL	22			
(21) RECONSTRUCTED, LOW CONFIDENCE LEVEL (22) RECONSTRUCTED, MODERATE CONFIDENCE LEVEL (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL	29 30		63 64	
NOT RECONSTRUCTED BECAUSE				
(02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ OVERRIDE (04) ROLLOVER (05) VAULTING (06) OTHER TRAVEL IN MORE THAN ONE PLANE (07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT (10) OTHER: (11) AT LEAST ONE VEHICLE	*			
BEYOND SCOPE (12) OTHER VEHICLE NOT INSPECTED				
MODE  (1) CDC ONLY (2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC (4) TRAJECTORY & CDC & DETAILED DAMAGE (5) NOT RECONSTRUCTED  COMPUTER PROGRAM	<b>2</b> 31		<del></del> 65	
SPECIFY:				

Module <u>C</u> <u>R</u> Format <u>0</u> <u>3</u>

CRASH RECONSTRUCTION

CR-3

NOTES:

- 1. ENTER CRASH RECONSTRUCTION DAMAGE MEASUREMENTS IN CENTIMETERS.
- 2. MEASURE C  $_1$  TO C  $_6$  FROM DRIVER TO PASSENGER SIDE IN FRONT OR REAR IMPACTS, REAR TO FRONT IN SIDE IMPACTS.

CASE VEHICLE


**LOCATOR** 

3. D IS POSITIVE IF MEASURED TO A POINT FORWARD OF OR TO THE RIGHT OF THE CG.

4. USE THE CENTER OF THE WHEELBASE AS THE CG.

Locate the end of the damage with respect to the vehicle longitudinal center line, or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage	Location of Field L
	Begins (B) front bunger corner	B.C. to B.C.
	and the state of t	



DL <u>[60</u>

PLANE:

- (1) Bumper
- (2) Above Bumper
- (3) Sill
- (4) Above Sill
- (5) Other Averaged
- (9) Unknown

# **CRUSH PROFILE IN CENTIMETERS**

	NOTE: Each line in the table below is a separate record (card).  Duplicate columns 1 - 12 for each completed line.										
Specific Impact Number	Plane of Impact C-Measur.		Damage Max	Field	C <sub>1</sub>	C <sub>2</sub>	C <sub>3</sub>	C <sub>4</sub>	C <sub>5</sub>	C <sub>6</sub>	±D
Number	Bumper	100	Crush	142	15	6	5	24	16	24	401
	-Freespace			110	-10	5	-0 5	-0 24	15	-10	t21
<del>-</del>	Above bumper		45		15	13	28	42	48	61	
	-Freespaul		15		- 16 0	-11 2	-10 18	-10 32	-II	-16 45	
	Sum Aveaged		-		N/A	N/A	23	N/A	52	59 30	
	Strindine adj		-3		-3	-3	-3	-3	- 3	-3	
1	5	ΙΦΦ	042	142	000		009	021	<b>Ф</b> 23	ወධን	+021
13	14	15 16 17	18 19 20	21 22 23	24 25 26	27 28 29	30 31 32	33 34 35	36 37 38	39 40 41	42 43 44 45
				: 							
				·							
2											

Module <u>C</u> <u>R</u> Format <u>0</u> <u>4</u>

CRASH RECONSTRUCTION

OTHER VEHICLE

CR-4

NOTES:


- 1. ENTER CRASH RECONSTRUCTION DAMAGE MEASUREMENTS IN CENTIMETERS.
- 2. MEASURE C  $_{\rm 1}$  TO C  $_{\rm 6}$  FROM DRIVER TO PASSENGER SIDE IN FRONT OR REAR IMPACTS, REAR TO FRONT IN SIDE IMPACTS.


LOCATOR

- 3. D IS POSITIVE IF MEASURED TO A POINT FORWARD OF OR TO THE RIGHT OF THE CG.
- 4. USE THE CENTER OF THE WHEELBASE AS THE CG.

Locate the end of the damage with respect to the vehicle longitudinal center line, or an undamaged axle for side impacts.

Location of Direct Damage	Location of Field L
Begin Orear bumper corner	B.C. to B.C.





DL <u>100</u>

PLANE:

- (1) Bumper
- (2) Above Bumper
- (3) Sill
- (4) Above Sill
- (5) Other \_\_\_\_
- (9) Unknown

**CRUSH PROFILE IN CENTIMETERS** 

	NOTE: Each line in the table below is a separate record (card). Duplicate columns 1 - 12 for each completed line.										
Specific Impact Number	Plane of Impact C-Measur.		Damage Max Crush	Field L	C <sub>1</sub>	C <sub>2</sub>	C <sub>3</sub>	C <sub>4</sub>	C <sub>5</sub>	C <sub>6</sub>	±D
1	Bumper	100	CI	177	15	6	9	l	Ø	Ø	-40
	Bumper Stringlinead -Freespace				+2	+2	+2	+2	+2	+2	
_	-Freespace				~2	Ø	Ø	Ф	Ø	-2	
1		100	015	177	Q15	008		003	002	000	-040
13	14	15 16 17	18 19 20	21 22 23	24 25 26	27 28 29	30 31 32	33 34 35	36 37 38	39 40 41	42 43 44 45
2											

Duplicate columns 1-8 from the previous card.  Module W T 9 10	Format <u>0</u>		WHEELS AND TIRES WT-1
WHEELSDAMAGED  (0) NO (1) YES (9) UNKNOWN	LF RF RR LR		SIZE (NOT DOT CODE. IF UNKNOWN, USE 9'S)  LF $\frac{P}{25}$ $\frac{3575R15}{5}$ RF $\frac{P}{35}$ $\frac{3575R15}{5}$ RR $\frac{P}{45}$
TIRE TREAD TYPE  (1) REGULAR (2) SNOW (3) SLICKS (4) ALL WEATHER (MS) (7) OTHER: (9) UNKNOWN	LF RF RR LR	4 17 4 4 4 4 20	ER P 23575R15_
CARCASS CONSTRUCTION  (1) BIAS (2) BELTED BIAS (3) RADIAL (4) ELLIPTICAL (5) HI PRESSURE SPARE (6) SPACE SAVER SPARE (7) OTHER: (9) UNKNOWN	LF RF RR LR	3 21 3 3 3 24	
IF VEHICLE IS EQUIPPED WITH DUAL WHEELS, COMPLETE FOR OUTER WHEELS AND MAKE NOTES ON INNER WHEELS. NOTES:		 	

Duplicate columns 1-8 Module F T Format 0 from the previous card. 9 10 11		FUEL AND FUEL TANKS	FT-1
TYPE OF PROPULSIVE FUEL  (1) GASOLINE (2) DIESEL OIL (3) LPG (4) ELECTRIC (7) OTHER: (9) UNKNOWN	13	AUXILIARY TANK TYPE  (1) OEM TANK (2) AFTER MARKET TANK (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	21
MAIN TANK LOCATION	322	AUXILIARY TANK LOCATION	<b>888</b> 22 24
MAIN FILLER CAP LOCATION	113	AUXILIARY FILLER CAP LOCATION	<b>298</b> 25 27
MAIN TANK MATERIAL	20	AUXILIARY TANK MATERIAL	28

# TANK AND FILLER CAP LOCATION CODES

# FIRST DIGIT (LONGITUDINAL)

- (1) BEHIND KICK-UP
- (2) IN KICK-UP
- (3) BETWEEN KICK-UP & COWL
- (4) FORWARD OF COWL
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

## SECOND DIGIT (LATERAL)

- (1) LEFT OF FRAME
- (2) WITHIN FRAME OR CENTERED
- (3) RIGHT OF FRAME
- (4) DUAL, RIGHT & LEFT TANKS
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

# THIRD DIGIT (VERTICAL)

- (1) BELOW FRAME
- (2) WITHIN FRAME OR CENTERED
- (3) ABOVE FRAME
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

# TANK MATERIAL CODES

- (1) STEEL
- (2) ALUMINUM
- (3) PLASTIC
- (7) OTHER
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

Duplicate	columns 1-8
from the	previous card.

Module	E	上	Format 0	_1
	٥	10		12

# FUEL LEAKAGE

# FL-1

# DID FUEL LEAKAGE RESULT FROM A CRASH EVENT

(0) NO KNOWN LEAKAGE SKIP PAGE.



(1) YES COMPLETE PAGE.

	l	11	111	IV	V	-
LEAK NUMBER	LEAKING COMPONENT	COMPONENT SOURCE	TYPE OF DAMAGE	SEVERITY OF DAMAGE	LOCATION OF LEAK	EVENT NUMBER
#1	14 15					21
#2	22 23		<u></u>	_		29
#3	30 31				<del></del>	37
#4	38 39			<del></del>		45
#5	46 47					53

# **I LEAKING COMPONENT**

# TANK AREA

- (11) MAIN FUEL TANK (INCLUDING VAPOR RECOVERY DOME)
- (12) AUXILIARY FUEL TANK
- (13) MAIN TANK FILLER TUBE
- (14) MAIN TANK CAP (GAS CAP)
- (15) AUXILIARY TANK FILLER TUBE
- (16) AUXILIARY TANK CAP (GAS CAP)
- (19) TANK AREA, DETAILS UNKNOWN

#### **DELIVERY SYSTEM**

- (21) FUEL FEED LINE (MAIN TANK TO FUEL PUMP)
- (22) FUEL FEED LINE (AUXILIARY TANK TO FUEL PUMP)
- (23) FUEL RETURN LINE (FUEL PUMP TO TANK)
- (24) INLINE FUEL FILTER
- (25) FUEL LINE (PUMP TO CARBURETOR OR INJECTOR PUMP)
- (26) CARBURETOR TO INJECTOR PUMP
- (27) FUEL PUMP
- (29) DELIVERY SYSTEM, DETAILS UNKNOWN

# EVAPORATIVE EMISSION CONTROL SYSTEM

- (31) ATMOSPHERIC VENT PIPE (NON-EEC EQUIPPED)
- (32) EEC PIPE (VAPOR CANISTER TO CARBURETOR)

#### **EEC SYSTEM (CONTINUED)**

- (33) VAPOR RECOVERY HOSES (CANISTER TO CARBURETOR)
- (34) LIQUID-VAPOR SEPARATOR (UNLESS PART OF TANK)
- (35) CANISTER
- (39) EEC SYSTEM, DETAILS UNKNOWN
- (49) ENGINE COMPARTMENT, COMPONENT UNKNOWN
- (99) COMPONENT UNKNOWN

# I COMPONENT SOURCE

- (1) OEM
- (2) AFTER MARKET
- (9) UNKNOWN

# III TYPE OF DAMAGE

- (1) DENTED/CRUSHED
- (2) PUNCTURED
- (3) RUPTURED
- (4) SEVERED/GROSS TEARS
- (5) DISCONNECTED/DEFEATED
- (9) UNKNOWN

# IV SEVERITY OF DAMAGE

- (1) MINOR
- (2) MODERATE
- (3) SEVERE
- (4) DISCONNECTED/DEFEATED
- (9) UNKNOWN

# V LOCATION OF LEAK

FIRST DIGIT (LONGITUDINAL LOCATION)

- (1) F, FORWARD OF COWL
- (2) P, BETWEEN COWL & REAR BULKHEAD
- (3) B, BEHIND REAR BULKHEAD
- (4) Y, F, & P
- (5) Z, P, & B
- (6) D, DISTRIBUTED (F, P & B)
- (9) UNKNOWN

# SECOND DIGIT (LATERAL LOCATION)

- (1) L, LEFT
- (2) C, CENTER
- (3) R, RIGHT
- (4) Y, LEFT CENTER (L & C)
- (5) Z, RIGHT CENTER (R & C)
- (6) D, DISTRIBUTED (F, P & B)
- (9) UNKNOWN

Duplicate columns 1-8 Module F R Format 0 11		FIRE	FR-1
WAS THERE FIRE IN  (0) NO <u>SKIP</u> PAC  (1) YES <u>COMPLE</u>	GE.	CASE VEHICLE?	
DID FIRE START IN CASE VEHICLE?  (0) NO (1) YES (9) UNKNOWN	14	SEVERITY OF FIRE DAMAGE  (1) MINOR (2) MODERATE (3) SEVERE (9) UNKNOWN	16
FLAME PROPOGATION RATE  (1) RAPID/EXPLOSIVE (2) SLOW/MODERATE (9) UNKNOWN	15	DID AN INJURY TO CASE VEHICLE OCCUPANT RESULT FROM FIRE IN OR ON CASE VEHICLE?  (0) NO (1) YES (9) UNKNOWN	17

PROVIDE NOTES IF FIRE OCCURRED.


Duplicate columns 1-8 Module E D Format 0 from the previous card. 9 10 11		ED-1
HOOD PERFORMANCE  FOR THE FOLLOWING, USE CODES:	STEERING COL FLEXIBLE COUPLING FLEXIBLE COUPLING TYPE	
(0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	(0) NONE (1) FLEXIBLE MATERIAL (2) POT (3) SINGLE U-JOINT (4) DOUBLE U-JOINT (5) FLEXIBLE CABLE (6) COMBINATION OF ABOVE (CIRCLE EACH)	9 26
HOOD LATCH <i>(ES)</i> RELEASED	(7) OTHER: (8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN, IF EQUIPPED	
-DAMAGED	<u>f</u>	
-JAMMED	14 COUPLINGDAMAGED  (USE CODES FROM HOOD PERFORMANCE) -SEPARATED (COMPLETE)	9 27 9 28
HOOD HINGESLEFT, DAMAGED	16	
-LEFT, SEPARATED (COMPLETE)	<b>♥</b>	
-RIGHT, DAMAGED	ENG COMPART TELESCOPING UNIT	
-RIGHT, SEPARATED (COMPLETE) HOOD REMAINED ON VEHICLE	19 (00) NONE INSTALLED (01) - (07) SEE UNITS ON PAGE ED-2 (88) NOT COLLECTED (97) OTHER: (98) EQUIPPED, TYPE UNKNOWN (99) UNKNOWN IF EQUIPPED	8 8 30
REAR EDGE OF HOODELEVATED	ORIGINAL LENGTH (mm)	
CONTACTED WINDSHIELD	<b>8</b> F (OR H):	
-PENETRATED WINDSHIELD	F (OR H):  TELESCOPED LENGTH (mm)  G:	
HOOD LATCH LOCATION		
(1) FRONT OF VEHICLE (2) COWL AREA	DIFFERENCE (mm)	
(3) SIDE (8) NOT APPLICABLE	24 F (OR H) - G	
(9) UNKNOWN	(IF LESS THAN 15mm, ENTER *000*.)	
ENGINE OR TRANSMISSION MOUNT  SEPARATION (COMPLETE)  (0) NO (1) YES (9) UNKNOWN	(888) NOT COLLECTED (991) NOT MEASURED/NO COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8 33

		EXTERIOR DAMAGE	ED-2
LEFT-SIDE BODY MOUNT DID BODY MOUNT SEPARATE?  (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN  LEFT PILLARS	<b>8</b> 34	LEFT DOORS  HOW DID DOORS  OPEN DURING COLLISION?  USE CODES:  (0) DOOR DID NOT OPEN	
PILLARS SEPARATED COMPLETELY -  USE CODES:  (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN		OPENED BECAUSE OF  (1) HINGE AREA SEPARATION (2) DOOR-LATCH SEPARATION (3) LATCH-STRIKER SEPARATION (4) STRIKER-PILLAR SEPARATION (5) BODY DISTORTION (6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OPENED, REASON UNKNOWN	
-A-PILLAR, UPPER LOWER	35 Ф 36	(8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN -FRONT	Ø 43
-B-PILLAR, UPPER LOWER	<b>9</b> 37 <b>0</b> 38	DOORS JAMMED CLOSED-  USE CODES:  (0) NO (1) YES	
-C-PILLAR, UPPER - LOWER	<b>1</b> 39 <b>1</b> 40	(8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN -FRONT	<b>Q</b> 45 <b>Q</b> 46
-D-PILLAR, UPPER LOWER	<b>Q</b> 41 <b>Q</b> 42		

# REAR DOOR

## **REAR DOOR TYPE**

- (0) NO DOOR (INCLUDES PICKUPS)
- (1) HATCHBACK
- (2) ONE-WAY TAILGATE
  (3) TWO-WAY TAILGATE
- (4) CLAMSHELL/DISAPPEARING **TAILGATE**
- SINGLE DOOR
- (6) DOUBLE DOOR
- (9) UNKNOWN



Clamshell



Double door

Single door



#### **HOW DID DOOR OPEN DURING COLLISION?**

(0) DOOR DID NOT OPEN

#### **OPENED BECAUSE OF**

- (1) HINGE AREA SEPARATION
- (2) DOOR-LATCH SEPARATION
- (3) LATCH-STRIKER SEPARATION (4) STRIKER-PILLAR SEPARATION
- (5) BODY DISTORTION
- (6) COMBINATION OF ABOVE (CIRCLE EACH)
- (7) OPENED, REASON UNKNOWN
- (8) NOT APPLICABLE (NO DOOR)
- (9) UNKNOWN

# DOOR JAMMED CLOSED

- (1) YES
- (8) NOT APPLICABLE (NO DOOR)
- (9) UNKNOWN

# OTHER REAR DAMAGE

# WAS PARTITION TO LUGGAGE AREA DAMAGED DURING COLLISION?

- (1) YES
- (8) NOT APPLICABLE
- (9) UNKNOWN

#### SPARE TIRE

- (0) NO SPARE TIRE
- (1) NOT ATTACHED BEFORE COLLISION
- (2) ATTACHED, NOT SEPARATED IN COLLISION
- (3) ATTACHED, SEPARATED DUE TO COLLISION
- (8) NOT COLLECTED
- (9) UNKNOWN

#### TRAILER HITCH TYPE

(0) NO HITCH

#### **BALL-AND-SOCKET TYPES**

- (1) TEMPORARY FRAMEWORK (E.G. RENTAL CLAMP-ON)
- (2) BUMPER-MOUNT ONLY (E.G. LIGHT TRUCK)
- (3) BUMPÉR-AND-FRAME (BUT NON-EQUALIZING)
- (4) LOAD EQUALIZING

## OTHER TYPES

- (5) RING-AND-PINTLE
- (6) FIFTH-WHEEL (INCL. P/U)
- (7) OTHER (E.G. CLEVIS-AND-PIN)
- (8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN IF EQUIPPED

# TRAILER TYPE (AT TIME OF COLLISION)

- (0) NO TRAILER
- (1) TRAVEL-TRAILER/CAMPER
- (2) MOBILE HOME
- (3) BOAT/SNOWMOBILE/ATV TRAILER
- (4) UTILITY TRAILER
- (5) TOWED CAR
- (7) OTHER:
- (8) TRAILER, TYPE UNKNOWN
- (9) UNKNOWN



0












O

		EXTERIOR DAMAGE E	ED-4
RIGHT-SIDE BODY MOUNT DID BODY MOUNT SEPARATE?  (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>8</u>	RIGHT DOORS  HOW DID DOORS OPEN DURING COLLISION?  USE CODES:	
RIGHT PILLARS  PILLARS SEPARATED COMPLETELY -  USE CODES:  (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN		(00) DOOR DID NOT OPEN  OPENED BECAUSE OF  (01) HINGE AREA SEPARATION (02) DOOR-LATCH SEPARATION (03) LATCH-STRIKER SEPARATION (04) STRIKER-PILLAR SEPARATION (05) BODY DISTORTION (06) COMBINATION OF ABOVE  - (CIRCLE EACH) (07) OPENED, REASON UNKNOWN (11) VAN RIGHT-REAR DOOR OPENED (ANY MECHANISM)	
-A-PILLAR, UPPER LOWER	55 <b>Q</b> 56	(98) NOT APPLICABLE (NO DOOR) (99) UNKNOWN -FRONT	<u>@</u> <u>@</u>
-B-PILLAR, UPPER	<u>Ø</u>	DOORS JAMMED CLOSED-	65 66
LOWER	<b>©</b> 58	USE CODES:  (0) NO (1) YES (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	
-C-PILLAR, UPPER	59 <b>Q</b> 60	-FRONT	<b>Q</b> 67
-D-PILLAR, UPPER	<b>Q</b> 61		68
LOWER	<b>©</b> 62	VAN REAR DOOR TYPE  (0) VAN, NO REAR DOOR (1) TRACK (SLIDING) - RIGHT SIDE (2) SINGLE-HINGED - RIGHT SIDE (3) DOUBLE-HINGED - RIGHT SIDE (4) TRACK (SLIDING) - RIGHT & LEFT SIDE (5) SINGLE-HINGED - RIGHT & LEFT SIDE (6) DOUBLE-HINGED - RIGHT & LEFT SIDE (7) TRACK AND HINGED COMBINATION (8) NOT APPLICABLE (NOT A VAN) (9) UNKNOWN	<b>8</b> 69



Duplicate columns 1-8 from the previous card.  Module S C Format 0 11	STEERING WHEEL AND COLUMN S	SC-1
STEERING WHEEL	STEERING WHEEL POSITION AT TIME OF COLLISION	
(0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN	IN WHAT O'CLOCK POSITION WAS THE  NORMAL TOP OF THE WHEEL POINTED  WHEN THE COLLISION OCCURRED?  EXAMPLES  O'CLOCK = 1 2 O'CLOCK = 0 2	
NUMBER OF STEERING WHEEL SPOKES (9) UNKNOWN	(NORMAL STRAIGHT AHEAD) O'CLOCK - LO	Jan
STEERING WHL SPOKE DAMAGE  (0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN	STEERING WHEEL ENERGY ABSORBING DEVICE  (1) EXAMPLES:  BARRACUDA, 70-74 CHALLENGER, 70-74 CAPRI, 71-77	
STEERING COLUMN OPTIONS	(2) EXAMPLES:  OMNI, 78 -  HORIZON, 78 -	
TILT FEATURE  (0) NOT EQUIPPED (1) YES, EQUIPPED, UNK POSITION (2) UP  (3) MIDDLE (4) LOWER (9) UNKNOWN IF EQUIPPED	TYPE OF DEVICE  (0) NONE (1) CONVOLUTED OR MESH CYLINDER (2) DEEP DISH STEERING WHEEL (7) OTHER: (8) NOT COLLECTED (9) UNKNOWN IF EQUIPPED  ORIGINAL DIMENSION (mm)	8 19
SWING-AWAY FEATURE  (0) NOT EQUIPPED  (1) YES, EQUIPPED  (9) UNKNOWN IF EQUIPPED	A: DAMAGE DIMENSION (mm)  B: DIFFERENCE (mm)	
TELESCOPING FEATURE  (0) NOT EQUIPPED  (1) YES, EQUIPPED  (9) UNKNOWN IF EQUIPPED	A - B  (888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO MEASURE (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8

	<del>-</del>	STEERING WHEEL AND COLUMN SC-2
STEERING COLUMN ENERGY ABSORBING DEVICE		STEERING WHEEL (CONTINUED)
TYPE OF DEVICE * (IF 27 OR 28)  (00) NOT EQUIPPED (88) NOT COLLECTED (99) UNKNOWN	8 8 24	STEERING WHEEL HUB DAMAGE  (0) NONE (1) OCCUPANT CONTACT (2) AIRBAG  (3)
ORIGINAL LENGTH (mm)  C:  COMPRESSED LENGTH (mm)		(3) OTHER
D:	8 8 8 27	
(888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT SEPARATION (992) SEPARATED, AMOUNT UNKNOWN (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8	
COLUMN VERTICAL ROTATION  (0) NO APPARENT ROTATION (1) UPWARD APPARENT ROTATION (2) DOWNWARD APPARENT ROTATION (9) UNKNOWN	<u> </u>	
COLUMN LATERAL ROTATION  (0) NO APPARENT ROTATION  (1) LEFT APPARENT ROTATION  (2) RIGHT APPARENT ROTATION  (9) UNKNOWN	<b>Ф</b> <u>3</u> 2	

# 1 = Definitely 2 = Probably 3 = Possible

						Intrus	ION IT-1
		(All Measurements Are in Centimeters)				Dominant	
Location of		Comparison	_	Intruded	=		Crush
Intrusion	Intruded Component	Value		Value		Intrusion	Direction
			_	_			
	None Apparent				=		
					=		
					=		
			_				
			_		=		
			_		=		
			_		=		
			_		=		
			_		=		
			_		_		
			_		=		
			_		=		

# OCCUPANT CONTACT WORKSHEET


					Confidence
	Interior	Occupant	Body		Level of
	Component	No. if	Region		Contact
Contact	Contacted	Known	if Known	Supporting Physical Evidence	Point
Α	Sunroof molding	1	Head	Hair deposits	1
B	Sunvisor	1	Head/face	Skin deposit & vanity mirror broken	1
С	Windshield	11	Hand	Spider web pattern	1
D	Knee bolster	1	Knee	Cracked & scuff mark	1
E					
F					
G					
- H					
1					
J					
K					

# 1 = Definitely 2 = Probably 3 = Possible

			SION IT-1		
		(All Measu	Dominant		
Location of		Comparison _	Intruded	_	Crush
Intrusion	Intruded Component	Value	Value	Intrusion	Direction
		_		=	
	None Apparent	_		=	
		_		=	
		_		=	
		_		=	
		_		=	
		_		=	
		_		=	
		_		=	
		-		=	
		_		=	
		-		=	

# OCCUPANT CONTACT WORKSHEET

					Confidence
	Interior	Occupant	Body		Level of
	Component	No. if	Region		Contact
Contact	Contacted	Known	if Known	Supporting Physical Evidence	Point
Α	Sunroof molding	1	Head	Hair deposits	1
B	Sunvisor	1	Head/face	Skin deposit & vanity mirror broken	1
· C	Windshield	1	Hand	Spider web pattern	1
D	Knee bolster	1	Knee	Cracked & scuff mark	1
· E					
F					
G					
- H					
İ					
J					
K					



# CODES FOR COLUMN B, OCCUPANT SPACE NUMBER

OCCUPANT SPACE NUMBER IS A TWO-DIGIT CODE. THE USE OF THE CODE IS DETERMINED BY THE VEHICLE SEAT CONFIGURATION AT THE TIME OF THE ACCIDENT.

#### **FIRST DIGIT**

THE FIRST DIGIT (LEFT DIGIT) DENOTES THE SEAT ROW, WITH CODE VALUES FROM 1 TO 5.

#### SECOND DIGIT

THE SECOND DIGIT (RIGHT DIGIT) DENOTES THE POSITION ON THE SEAT AND, IN SOME INSTANCES, THE WIDTH OF THE SEAT.


(1) LEFT	(3) RIGHT	•••••	INDIVIDUAL SEAT
(1) LEFT	(2) CENTER	(3) RIGHT	BENCH: FULL WIDTH 3 PASSENGER
(1) LEFT	(2) LEFT CENTER	(6) RIGHT (3) RIGHT	BENCH: FULL WIDTH 4 PASSENGER
(1) LEFT	(2) CENTER	(5) RIGHT &AISLE SPACE	BENCH: PARTIAL WIDTH, LEFT
(0) LEFT & SPACE	(2) CENTER	(5) RIGHT &SPACE	BENCH: PARTIAL WIDTH, CENTERED
(4) ENTIRE V	VEHICLE WIDTH		CARGO AREA

#### **EXAMPLES**

THE TWO FIGURES BELOW PROVIDE EXAMPLES OF THE OCCUPANT SPACE NUMBER.

#### PASSENGER CAR 5 PASSENGERS

#### VAN 12 PASSENGER CAPACITY



# CODES FOR COLUMN F, MEASUREMENT AXIS

(X) X-AXIS (FORE & AFT)

(Y) Y-AXIS (LATERAL)

(Z) Z-AXIS (VERTICAL)

# CODES FOR COLUMNS G, H, I & J, OCCUPANT & INJURY NUMBERS

OCCUPANT NUMBER	INJURY NUMBER	CONTACT
(00)	(00)	NO CONTACT
(##)	(00)	CONTACT, NO INJURY
(97)	(99)	CONTACT, OCCUPANT UNKNOWN, INJURY UNKNOWN
(99)	(00) OR (99)	UNKNOWN IF CONTACT

#### CODES FOR COLUMN C, INTRUDING COMPONENT OR OBJECT

NOTE: DO NOT CODE OBJECTS OTHER THAN COMPONENTS OF CASE VEHICLE.

#### INDIVIDUAL COMPONENT

#### INTERNAL

- (01) INSTRUMENT PANEL
- (02) FIRE WALL
- (03) TOE PAN
- (04) FLOOR PAN
- (05) STEERING COLUMN
- (06) WINDSHIELD
- (07) WINDSHIELD HEADER
- (08) A-PILLAR
- (09) DOOR PANEL OR SIDE PANEL
- (10) WINDOW FRAME
- (11) B-PILLAR
- (12) C-PILLAR
- (13) D-PILLAR
- (14) ROOF SIDE RAILS
- (15) ROOF OR CONVERTIBLE TOP
- (16) BACKLIGHT HEADER
- (17) FRONT SEAT-BACK SURFACE/ SEAT-BACK BACK SURFACE
- (18) SECOND SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (19) THIRD SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (20) FOURTH SEAT-BACK SURFACE
- SEAT-BACK BACK SURFACE
  (21) FIFTH SEAT-BACK SURFACE
  SEAT-BACK BACK SURFACE
- (22) BACK PANEL/BACK DOOR SURFACE
- (23) SEAT CUSHION SURFACE/EDGE
- (24) CONSOLE
- (25) OTHER (DESCRIBE)
- (26) UNKNOWN INTERNAL SURFACES
- (28) TRANSMISSION TUNNEL (HUMP)
- (29) SIDE FOOTWELL PANEL (KICKPANEL)
- (30) SILL

#### **EXTERNAL**

- (43) HOOD
- (44) OBJECT EXTERNAL TO PASSENGER COMPARTMENT BUT PART OF CASE VEHICLE
- (45) OUTSIDE SURFACE OF CASE VEHICLE
- (46) OTHER (E.G. SPARE TIRE, JACK. DESCRIBE.)
- (49) UNKNOWN EXTERNAL OBJECT

#### GROUPED FOR MASSIVE INTRUSION INTO AN OCCUPANT SPACE

USE ONLY IF ALL THESE COMPONENTS
INTRUDED INTO A SINGLE OCCUPANT SPACE.

- (50)WINDSHIELD HEADER A-PILLAR
  - ROOF SIDE RAIL
- (51)INSTRUMENT PANEL A-PILLAR DOOR PANEL
- (52)INSTRUMENT PANEL A-PILLAR

WINDSHIELD HEADER

- (53)DOOR PANEL B-PILLAR ROOF RAIL
- (54)DOOR PANEL A-PILLAR ROOF RAIL
- (55)INSTRUMENT PANEL FLOOR PAN A-PILLAR DOOR FRAME
- (56)ROOF RAIL A-PILLAR B-PILLAR WINDOW FRAME
- (57)ROOF RAIL
  A-PILLAR
  B-PILLAR
  C-PILLAR
  DOOR PANEL
- (58)ROOF ROOF RAIL WINDOW FRAME DOOR PANEL
- (59)BACKLIGHT HEADER ROOF C-PILLAR THIRD SEAT-BACK

(60)ROOF
ROOF RAIL
A-PILLAR
B-PILLAR
C-PILLAR
WINDOW FRAME
DOOR PANEL

FLOOR PAN

- (61)INSTRUMENT PANEL TOE PAN WINDSHIELD HEADER A-PILLAR ROOF RAIL WINDOW FRAME DOOR PANEL ROOF
- (62)ROOF
  ROOF RAIL
  C-PILLAR
  WINDOW FRAME
  FLOOR PAN
  SECOND SEAT
  DOOR PANEL
- (63)ROOF RAIL
  ROOF
  B-PILLAR
  WINDOW FRAME
  FLOOR PAN
  DOOR PANEL
  SECOND SEAT
  FRONT SEAT
- (64)ROOF RAIL
  ROOF OR CONVERTIBLE TOP
  A-PILLAR
  B-PILLAR
  WINDOW FRAME
  WINDOW HEADER
- (65)WINDSHIELD WINDSHIELD HEADER ROOF SIDE RAIL
- (66)WINDSHIELD WINDSHIELD HEADER A-PILLAR

(98)NOT APPLICABLE

(99)UNKNOWN

Duplicate columns 1-8 Module from the previous card.	<u>I</u> <u>T</u> Format <u>0</u> <u>1</u> 12		ln.	ITRUSION IT-5
WAS THERE OCCUPANT COM  (0) NO <u>DO NOT</u> ANSWER NEX  (1) YES <u>ANSWER</u> NEXT QUEST  (9) UNKNOWN <u>SKIP PAGE</u> .	T QUESTION. <u>SKIP PAGE</u> .	y <b>(</b>	VAS INTRUSION CATA (0) NO <u>COMPLETE</u> (1) YES <u>SKIP</u> PAGE	PAGE.
Duplicate columns 1-8 Module from the previous card.  NOTE: Each line in the table below	<u>I</u> <u>T</u> Format <u>0</u> <u>2</u> 9 10 11 12 is a separate record (card).	Duplicate column	s 1 - 12 for each complete	ed line.
CODES F	TRUSIONS IN THIS ORDER: FOR B, F, G, H, I, J ON PAI FOR C ON PAGE IT-4		ON ROW; FRONT TO B	
A B C INTRUDING INTRUSION OCC. COMPONENT NUMBER SPACE NO. OR OBJECT	D E F ASSOC. MAXIMUM MAXIMI EVENT INTRUSION INTRUS NO. X AXIS (cm) Y AXIS (	ION INTRUSION	H I OCCUPANT INJURY NUMBER NUMBER	
13-14 15-16 17-18	19 20-21 22-23	3 24-25	26-27 28-29	30-31 32-33
0 1				
02				
0 3				-
0 4				-
<u>0 5</u>				-
0 6				-
0 7 NOTE: USE ADDITIONAL PAGE IF MORE TH	IAN 7 INTRUSIONS.			-
Duplicate columns 1-8 Module from the previous card.	1 T Format 0 3 9 10 11 12			
NOTE: IF NO SIDE DOOR INTRUSION, SKIP REMAINDER OF PAGE.  SIDE DOOR INTRUSION RESULTED FROM	IF DAMAGE DOOR INTR INTRUSION NUMBER	TO DOOR CO SUSION, CODE DAMAGED COMPONENT 1	E COMPONENT DAMAGED	TED IN INCREASED  CODES FOR COMPONENTS
CODES	A		25 29 33	(0) NONE (1) A-PILLAR (2) B-PILLAR (3) C-PILLAR (4) LATCH/STRIKER (5) HINGES (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN
	34 35		37	

Duplicate columns 1-8 from the previous card.

Module | T Format 0 2 11 12

INTRUSION

IT-6

NOTE: Each line in the table below is a separate record (card).

Duplicate columns 1 - 12 for each completed line.

-- ADDITIONAL PAGE --

# INTRUSIONS CODE INTRUSIONS IN THIS ORDER: LEFT TO RIGHT ON ROW; FRONT TO BACK IN VEHICLES. CODES FOR B, F, G, H, I, J ON PAGE IT-3 CODES FOR C ON PAGE IT-4 OCCUPANT CONTACT AND INJURY

A INTRUSION NUMBER		C INTRUDING COMPONENT OR OBJECT	EVENT NO.	X AXIS (cm)	F MAXIMUM INTRUSION Y AXIS (cm)	Z AXIS (cm)	H OCCUPANT NUMBER	INJURY NUMBER	J OCCUPANT NUMBER	K INJURY NUMBER
13-14	15-16	17-18	19	20-21	22-23	24-25	26-27	28-29	30-31	32-33
0 8		<del></del>		<del></del>						
09										
10										
11		<del></del>								
1 2										
1 3										
1 4										
<u>1</u> <u>5</u>				<del></del>						
16						<del></del>	<u> </u>			
<u>1 7</u>						<del></del>				
1 8			_						<del></del>	
19										
2 0										
2 1			_							
2 2										
2 3										
2 4			_							
25										

	DES:					
	(0 (1	) NO ) YES ) NO, and	OCCUPANT CONTACT	(4) YES, and C (8) NOT APPLI (9) UNKNOWN		
	LEFT	RIGHT				
SIDES			FRONT		INSTRUMENT PANEL	
FRONT DOOR	Q	$ \underline{\boldsymbol{\omega}} $	, FOOT CONTROLS	<b>Ø</b>	UPPER PANEL	4
FRONT HARDWARE			IGNITION KEYS	45	MID PANEL	55 <b>D</b> 56
FRONT ARMREST	(D)		REAR VIEW MIRROR	0	LOWER PANEL	4 7 7
FRONT GLASS	<u>17</u>	20	SUNVISOR/FITTINGS	<u>5</u>	ASHTRAY	58
REAR DOOR AREA	21	22	<ul><li>(5) LEFT SIDE ONLY</li><li>(6) RIGHT SIDE ONLY</li><li>(7) BOTH SIDES</li></ul>		CONTROL KNOBS & LEVERS	<u>Ø</u>
REAR HARDWARE	<b>Q</b>	<b>Q</b>	WINDSHIELD TOP	M	GLOVE	
REAR ARMREST		<b>D</b>	MOLDINGS	49	COMPARTMENT AREA	
REAR GLASS	25	<b>Q</b> 28	LEFT A-PILLAR (UPPER OR LOWER)		INSTRUMENTS	
ROOF SIDE RAIL	27	<b>Q</b>	RIGHT A-PILLAR (UPPER OR LOWER)	$ \Phi $	PARKING BRAKE RELEASE	62
B-PILLAR	29	<b>Q</b> 32	CENTER CONSOLE	51	PARKING BRAKE PEDAL	Y SS
C-PILLAR	<b>2</b> 31	<b>Q</b> 34	TRANSMISSION	52	A/C OR UPPER VENT OUTLETS	
D-PILLAR	<b>Ø</b>	0	SELECTOR LEVER	53	HEATER OR A/C DUCTS	65
, HEADLINING	<b>Ö</b>	<b>@</b>	RIM, HORN, SPOKE	<b>Q</b> 54	RADIO	66
ROOF STRUCTURE	Ø	الله			OTHER: *	9
T-ROOF/SUN ROOF	39				<del></del>	. 67
OTHER: *	)  38 <b>7</b> 4 <b>8</b> 0   43				Rear	
· ·	43	44			WINDOW	0
		l				
-					WINDOW HEADER	69
					Consoles	
					VERTICAL	$ \mathcal{Q} $
					ROOF	70 71

<sup>\*</sup> MORE THAN ONE ITEM MAY BE NOTED.

Duplicate columns 1-8 Module S T from the previous card. 9 10		) <u>2</u> 1 12	SEATS	1	ST-1
FRONT SEAT	DRIVER	PASSENT	FRONT SEAT-BACK	Driver	PASSENT
TYPE OF FRONT SEAT  (00) NO SEAT  (01) STANDARD BENCH  (02) SPLIT BACK, 50-50  (03) SPLIT BACK, DRIVER WIDE  (04) SPLIT BACK, PASS. WIDE  (05) BUCKET  (06) CAPTAIN'S CHAIR  (07) INDIV. BENCH, 50-50  (08) INDIV. BENCH, DRIVER WIDE  (09) INDIV. BENCH, PASS. WIDE  (97) OTHER:	<u>Ø</u> 5	<u>Ø</u> <u>5</u>	SEAT-BACK TYPE  (1) FORWARD FOLDING  (2) RIGID  (3) RECLINING  (7) OTHER:	3 30	3 31
(99) UNKNOWN  TYPE OF SEAT MOUNT (1) STANDARD (2) PEDESTAL (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	17	18	(0) NONE (1) MANUAL (2) INERTIA (3) POWER (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	3	33
SWIVEL MECHANISM EQUIPPED (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	19	20	LOCKS HELD (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	34	35
ORIGINAL EQUIPMENT SEATS (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	21	22	RECLINER MECHANISM HELD (0) NO (1) YES	1	1
CONTACT OF SEAT BY REAR OCCUPANT (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<b>8</b> 23	8 24	(8) NOT APPLICABLE (9) UNKNOWN	36	
FRONT SEAT DAMAGE  (0) NONE  (1) BACKREST ONLY DAMAGED  (2) CUSHION ONLY DAMAGED  (3) BACKREST &  CUSHION DAMAGED  - (8) NOT APPLICABLE  (9) UNKNOWN	25	<u>Ø</u>	HEAD RESTRAINT  HEAD RESTRAINT TYPE  (0) NONE (1) ADJUSTABLE (2) INTEGRAL (3) NOT INTEGRAL, BUT CANNOT BE REMOVED (7) OTHER: (8) NOT APPLICABLE	38	39
CENTER ARMREST DAMAGED (0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE (NO CENTER ARMREST) (9) UNKNOWN IF EQUIPPED	<u></u>	)	(9) UNKNOWN  REMOVED PRE-CRASH (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	40	<u>B</u>
FRONT SEAT ROTATION  (0) NONE APPARENT	Ø	Ø	ADJUSTMENT AT CRASH (1) UP (2) DOWN (8) NOT APPLICABLE (9) UNKNOWN	8/42	$\frac{\mathcal{G}}{43}$
(0) NONE APPARENT (1) FORWARD APPARENT (2) REARWARD APPARENT (3) LEFT APPARENT (4) RIGHT APPARENT (5) MULTIPLE ROTATIONS SPECIFY (8) NOT APPLICABLE (9) UNKNOWN	28	29	HEAD RESTRAINT DAMAGE (0) NONE (1) DAMAGED BUT NOT SEPARATED (2) SEPARATED (8) NOT APPLICABLE (9) UNKNOWN	<u>~</u>	45


			Se	EATS	ST-2
FRONT SEAT ADJUSTMENT SEAT ADJUSTMENT TYPE  (0) NONE (RIGID) (1) MANUAL (2) POWER (7) OTHER: (8) NOT APPLICABLE (NO SEAT) (9) UNKNOWN  ADJUSTMENT PROVIDED (1) 2-WAY	2 46	PASSEN'R  2 47	SECOND SEAT (CONT.)  CENTER ARMREST DAMAGED  (0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE (NO CENTER ARMREST) (9) UNKNOWN IF EQUIPPED	4	<u>8</u>
(2) 4-WAY (3) 6-WAY (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN  SEAT ADJUSTER DAMAGE (0) NONE	48	49	SECOND SEAT-BACK  LOCKS  FOR THE FOLLOWING, USE:	LEFT	Rіднт
(1) CHUCKING (FREE PLAY) (2) DEFORMED (RELEASED/JAMMED) (3) SEPARATED (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN  SEAT ADJUSTER SEPARATION	50	<u>51</u>	(0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN  LEFT OR CENTER, EQUIPPED	<u></u>	<b>Ø</b>
(0) NONE (1) SEPARATED AT FLOOR (2) SEPARATION OF ADJUSTER (3) SEPARATED AT SEAT (8) NOT APPLICABLE (9) UNKNOWN  PRE-CRASH POSITION	52	<u>O</u> ₅₃	LEFT OR CENTER, HELD  (3) SEAT FOLDED DOWN  RIGHT, EQUIPPED  RIGHT, HELD	61 3 63 63 63 65 67	<b>8 1 3</b>
(1) FORWARD (2) MIDDLE (3) REARWARD (8) NOT APPLICABLE (9) UNKNOWN	<u>2</u>	55	(3) SEAT FOLDED DOWN THIRD SEAT		68
SECOND SEAT  TYPE OF SECOND SEAT  (0) NONE (1) NON-FOLDING	LEFT	RIGHT	EQUIPPED BACKREST DAMAGED	Ø 780 730 73	70 <b>8</b> 72
(2) FOLDING (3) CAPTAIN'S CHAIR (4) JUMP SEAT (5) INTEGRAL CHILD SEAT (6) LUGGAGE AREA ACCESS PANEL	$\frac{2}{56}$	$\frac{2}{57}$	CUSHION DAMAGED	73	74
(9) UNKNOWN  SECOND SEAT DAMAGE (0) NONE (1) BACKREST ONLY (DAMAGED OR LOOSENED) (2) CUSHION ONLY (DAMAGED OR LOOSENED) (3) BACKREST & CUSHION (DAMAGED OR LOOSENED) (4) INTEGRAL CHILD SEAT (PRIORITY CODE) (5) LUGGAGE AREA ACCESS PANEL (DAMAGED OR LOOSENED) (8) NOT APPLICABLE (9) UNKNOWN	<b>⊘</b> 58	<u>Ø</u>	VEHICLE EQUIPPED WITH REAR HEAD RESTRAINTS  (0) NOT EQUIPPED (OR REMOVED) (1) EQUIPPED (2) EQUIPPED & DAMAGED (8) NOT APPLICABLE (NO REAR SEAT) (9) UNKNOWN  Applies to any rear-seat position	7	5

Duplicate columns 1-8 Module A B Format C from the previous card.	1 12	AIRBAG	AB-1
DRIVER SIDE  LOCATION OF AIRBAG  STEERING WHEEL  EQUIPPED  (0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED	13	PASSENGER SIDE LOCATION OF AIRBAG INSTRUMENT PANEL (GLOVE BOX)  EQUIPPED  (0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED	16
DEPLOYED  (0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	14	DEPLOYED  (0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	17
CONDITION OF AIRBAG STEERING WHEEL  (0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE (NOT EQUIPPED/NOT DEPLOYED) (9) UNKNOWN IF EQUIPPED OR CONDITION	<u></u>	CONDITION OF AIRBAG INSTRUMENT PANEL (GLOVE BOX)  (0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE (NOT EQUIPPED/NOT DEPLOYED) (9) UNKNOWN IF EQUIPPED OR CONDITION	<u>Ø</u>
DRIVER SIDE  AIRBAG  STEERING WHEEL  TETHER  (0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED	19	PASSENGER SIDE  AIRBAG INSTRUMENT PANEL (GLOVE BOX)  TETHER  (0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED	21
MARKED BY CONTACT  (0) NO (1) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	<u>Ø</u>	MARKED BY CONTACT  (0) NO (1) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	<u>Q</u>

#### AIRBAG AB-2


#### AIRBAG NUMBER ON DRIVER SIDE:

# NOTE AND DESCRIBE ANY AIRBAG CONTACT OR DAMAGE ON DIAGRAM BELOW:



#### AIRBAG NUMBER ON PASSENGER SIDE:

# NOTE AND DESCRIBE ANY AIRBAG CONTACT OR DAMAGE ON DIAGRAM BELOW:



#### NOTE TO THE INVESTIGATOR:

THE FOLLOWING TWO SECTIONS,
OCCUPANT INFORMATION AND INJURY CLASSIFICATION,
ARE TO BE FILLED IN
FOR EACH CASE VEHICLE OCCUPANT,
WHETHER INJURED OR NOT.

IF THERE IS MORE THAN ONE OCCUPANT,
USE ADDITIONAL COPIES
OF PAGES OC-1, OC-2, OC-3,
AND IC-2 TO DESCRIBE THEM
AND ATTACH THE COPIES TO THIS REPORT.


Duplicate columns 1-8 Module O C Format O 11	OCCUPANT INFORMATION C	)C-1
OCCUPANT IDENTIFICATION OCCUPANT NUMBER  ROLE OF OCCUPANT AT 1ST IMPACT  (1) MOTOR VEHICLE DRIVER (2) MOTOR VEHICLE PASSENGER (NOT DRIVER) (9) UNKNOWN	PHYSICAL DESCRIPTION  AGE IN YEARS (00) LESS THAN 1 YEAR (98) 98 YEARS OR OLDER (99) UNKNOWN  AGE IN MONTHS (00) LESS THAN 1 MONTH (25) 25 MONTHS OR OLDER (99) UNKNOWN	$\frac{56}{20}$ $\frac{21}{21}$ $\frac{25}{22}$ $\frac{2}{23}$
OCCUPANT POSITION  ROW LOCATION  (1) FRONT (2) SECOND (3) THIRD (4) FOURTH (7) OTHER: (8) EXTERNAL TO PASSENGER COMPARTMENT (E.G. BED OF PICKUP) (9) UNKNOWN	MASS (kg) (999) UNKNOWN  HEIGHT (cm) (999) UNKNOWN  SEX (1) MALE (2) FEMALE (9) UNKNOWN	<u>096</u> 24 25 26  185 27 28 29  1 30
LATERAL LOCATION  (1) LEFT (2) LEFT CENTER (3) CENTER (4) RIGHT CENTER (5) RIGHT (6) ALL (LYING ON SEAT) (8) EXTERNAL TO PASSENGER COMPARTMENT (9) UNKNOWN	MEDICAL CONDITIONS  TREATMENT/MORTALITY  (00) NONE  (01) FIRST AID AT SCENE  (02) TREATED AT HOSPITAL/CLINIC  BUT NOT ADMITTED  (03) HOSPITALIZED FOR OBSERVATION  LESS THAN 24 HOURS  (04) HOSPITALIZED OVER 24 HOURS  OR FOR SIGNIFICANT TREATMENT  (05) FATAL, DEAD AT SCENE  (06) FATAL, DOA	<u>4</u> 31 32
POSTURE  (10) SITTING ON SEAT  (11) SITTING ON SEAT IN ABNORMAL POSITION (E.G. FEET ON DASH, SIDEWAYS)  (12) SITTING ON CONSOLE  (20) ON LAP OR IN ARMS  (30) STANDING ON SEAT  (40) STANDING ON FLOOR  (47) STANDING, EXTERNAL TO PASSENGER COMPARTMENT	(07) FATAL, DEAD WITHIN 24 HOURS (08) FATAL, DEAD 24 HOURS TO 31 DAYS LATER (09) FATAL, DEAD 31 DAYS TO 1 YEAR LATER (10) FATAL DEAD WITHIN UNKNOWN PERIOD (99) UNKNOWN  INJURY SEVERITY SCORE (ISS) (99) UNKNOWN	<u>√</u> <u>⊕</u> 33 34
(50) IN BASSINET (60) IN CHILD SEAT (65) IN CHILD HARNESS (70) LYING ON SEAT (80) LYING/SITTING ON PASSENGER FLOOR (83) LYING/SITTING ON OTHER OBJECT IN PASSENGER COMPARTMENT: (85) ON CARGO FLOOR/FOLDED SEAT-BACK (87) LYING/SITTING, EXTERNAL TO PASSENGER COMPARTMENT (97) OTHER: (99) UNKNOWN	NON-IMPACT MED. CONDITIONS  (0) NONE (1) YES, TIME & TYPE UNKNOWN (2) PRE-CRASH FATAL (CLINICAL DEATH AT WHEEL) (3) PRE-CRASH NON-FATAL (E.G. PRIOR INJURY, STROKE) (4) PREGNANT (5) POST-CRASH FATAL (DROWNING) (6) POST-CRASH NON-FATAL INJURY (7) OTHER: (8) COMBINATION OF ABOVE (CIRCLE EACH) (9) UNKNOWN	35

		OCCUPANT INFORMATION	OC-2
MEDICAL CONDITIONS (CONT.)  POLICE INJURY SEVERITY CODE FOR THIS OCCUPANT  (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO IMPACT (7) NON-FATAL INJURY, SEVERITY UNKNOWN (9) UNKNOWN	2 **	CHILD SEAT TYPE  (00) NONE USED (01) YES, USED (02) INTEGRAL, Chrysler Mini-van (88) NOT APPLICABLE (ADULT OR OLDER CHILD) (99) UNKNOWN  CHILD SEAT MAKE/MODEL	88
RESTRAINT SYSTEM  (0) NONE (1) LAP BELT (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (9) UNKNOWN  ACTIVE RESTRAINT SYSTEM USAGE (0) NONE (AVAILABLE BUT NOT USED) (1) LAP BELT ONLY (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (7) IMPROPER USAGE (8) NOT APPLICABLE (NONE AVAILABLE) (9) UNKNOWN  PASSIVE RESTRAINT SYSTEM  (0) NONE (1) AIRBAG INSTALLED (2) PASSIVE UPPER TORSO	3 37 <b>Q</b> 38	EJECTION  (0) NONE (1) PARTIAL (2) COMPLETE (7) EJECTED, DEGREE UNKNOWN (9) UNKNOWN IF EJECTED  AREA OF EJECTION  (01) WINDOW, LEFT SIDE (02) WINDOW, RIGHT SIDE (03) WINDOW, REAR (04) DOOR, LEFT SIDE (05) DOOR, RIGHT SIDE (06) DOOR, REAR OR TAILGATE (07) WINDSHIELD (08) ROOF OR OPEN CONVERTIBLE OR FROM EXTERNAL AREA (96) EJECTED AREA UNKNOWN (97) OTHER AREA: (98) NOT APPLICABLE (NOT EJECTED) (99) UNKNOWN IF EJECTED	<u>Q</u> 43
WITH KNEE BOLSTERS  (3) PASSIVE UPPER TORSO WITHOUT KNEE BOLSTERS  (4) PASSIVE LAP & UPPER TORSO (5) AIRBAG INSTALLED & PASSIVE RESTRAINT (7) OTHER: (9) UNKNOWN  PASSIVE RESTRAINT SYSTEM USAGE  (0) SYSTEM DEFEATED (1) AIRBAG NOT DEPLOYED (2) AIRBAG DEPLOYED (3) AIRBAG NOT REINSTALLED (4) PASSIVE UPPER TORSO USED (5) PASSIVE LAP & UPPER TORSO USED (6) SYSTEM USED IN MANUAL MODE (7) IMPROPER USAGE (8) NOT APPLICABLE (NOT ORIGINALLY EQUIPPED) (9) UNKNOWN	<b>2</b>	HEAD RESTRAINT HEAD RESTRAINT AVAILABLE FOR THIS POSITION  (0) NOT EQUIPPED OR REMOVED (1) EQUIPPED (9) UNKNOWN	46

		OCCUPANT INFORMATION (	OC-3
OCCUPANT EYEWEAR  (0) NONE (1) GLASSES (2) CONTACTS (3) BOTH GLASSES AND CONTACTS (4) OTHER (8) NOT APPLICABLE (9) UNKNOWN	47	SOURCE OF INFORMATION  (0) INTERVIEW (1) HOSPITAL (2) AUTOPSY (3) POLICE (4) OTHER (5) LAY CORONER/EXTERNAL EXAM (7) COMBINATION OF ABOVE (CIRCLE) (8) NOT APPLICABLE (9) UNKNOWN	7 48

### OCCUPANT INFORMATION OC-4

#### INDICATE LOCATION OF INJURIES.



Duplicate columns 1-8 from the previous card.

Module <u>I</u> <u>C</u> Format <u>0</u> <u>1</u> 12

INJURY CLASSIFICATION IC-1

NOTE: Each line in the table below is a separate record (card).


Duplicate columns 1 - 12 for each completed line.

#### OCCUPANT INJURY CLASSIFICATION

						PRIM	ARY (	OIC		А	ssoc	IATE	OIC		COMMENTS
OCCUPANT NUMBER	INJURY NUMBER	PLACE CONTACTS IN ORDER PROBABILITY (HORIZONTALL START WITH MOST PROBABI IN 1ST CONTACT AREA COLO AREA(S) OF POSSIBLE CONT 1ST 2ND			BODY REGION 1	ASPECT Q	LESION 3	SYSTEMIORGAN 4	SEVERITY 15	BODY REGION 1	ASPECT Q	LESION 3	SYSTEM/ORGAN 4	SEVERITY 15	
13-14	15-16	17-18	19-20	COMMENTS	21	22	23	24	25	26	27	28	29	30	
OL	Q1	25	10	Sun roof	E	<u>S</u>	A	Ī	1	_					
1	<u> </u>	87		visor	F	<u>C</u>	A	Ī	1	_	_		_		
	03	48			P	R	F	5	3						
	04	48			K	R						_	_		
						<u> </u>	_	_	_						
					_	_	_		_	_	_				
							_	_	_	_		_	_	_	
					_	_	_	_		_	_	_	_		
 gi					—	_			_	_		_		_	
r each ii					_					_	_	_	_		
te "Occupant Number" for each line.					_			_	_	_					
paņt Nu									_				_	_	
Doccu					_			_	_			_		_	
Duplicat												_			
										_					
														_	
-							_						_	-	
					_	_			-	_	_		_	-	
						-	_	_	-	_			_		
		<u> </u>			_			_				_		-	

#### CODES FOR AREAS OF POSSIBLE OCCUPANT CONTACT

FRONT	OF PASSENGER COMPARTMENT	. Cipeo	
	SUNVISOR, FITTING(S) &/OR TOP MOLDING	SIDES	CLIDEACE OF OUR INTERIOR
(12)	· · · · · · · · · · · · · · · · · · ·	(20)	
( •-/	WINDOWNELD	(19)	
(05)	INSTRUMENT PANEL (SPECIFIC AREA UNKNOWN)	. (13) (24)	
(54)		. (24)	COAT HOOK
(55)	· · ·	- (22)	MINDOM CLASS (CIDE)
(56)	· · · · · · · · · · · · · · · · · · ·	\ <del></del> /	
(81)	ASH TRAY (INSTRUMENT PANEL)	(21)	WINDOW FRAMES (SIDE)
(02)	GLOVE COMPARTMENT AREA	(26)	ROOF SIDE RAIL
(47)	AIRBAG (ACRS) COMPARTMENT DOOR/COVER	(14)	
(47)	THE DOOR OF THE PROPERTY OF TH	(15)	
(57)	BENEATH INSTRUMENT PANEL		C-PILLAR
(53)	PARCEL TRAY		D-PILLAR
(48)	KNEE RESTRAINT	(17)	D-FILLAN
(86)	VERTICAL CONSOLE	FLOOR	
(55)		(40)	FLOOR
(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)	(27)	
(,		(44)	
(09)	STEERING ASSEMBLY (SPECIFIC AREA UNKNOWN)	(85)	
(65)	STEERING WHEEL	(28)	
(66)	STEERING WHEEL COLUMN	(91)	
(59)	TRANSMISSION LEVER ON COLUMN	(31)	NOR! ANEL
(,		Roof	
(03)	HARDWARE ITEM (SPECIFIC AREA UNKNOWN)	(25)	ROOF OR CONVERTIBLE TOP
(82)	INSTRUMENT(S)	(10)	_ : - == : =:
(83)	CONTROL KNOB(S) & LEVER(S) (FRONT)	(26)	ROOF SIDE RAIL
(84)	PARKING BRAKE HANDLE IN FRONT	(24)	
(67)	IGNITION KEY	(18)	
(06)	MIRROR	(39)	
(04)	HEATER OR AIR CONDITIONING DUCTS	(68)	
(01)	AIR CONDITIONING OR VENTILATION OUTLET(S)	(69)	
(08)	RADIO (BUILT IN)	(00)	HOLL BAN
(58)	ADD-ON TAPE DECK, RADIO, A/C	FYTERIC	OR SURFACE OF CASE VEHICLE
(68)	ROOF MOUNTED CONTROLS/CONSOLES		OUTSIDE SURFACE OF CASE VEHICLE
(,		(0,7	(SPECIFIC AREA UNKNOWN)
REAR		(35)	HOOD OF CASE VEHICLE
(88)	SURFACE OF REAR INTERIOR	(60)	EXTERIOR OF CASE VEHICLE (E.G.
	REAR WINDOW	(00)	OUTSIDE MIRRORS, ANTENNA, TRIM)
(39)		(62)	EXTERIOR SIDE ROOF RAIL OF CASE VEHICLE
(50)		(63)	TRUNK LID OF CASE VEHICLE
<b>\</b> /		(64)	TIRES OF CASE VEHICLE
INTERIOR-GENERAL (64)			
	TRANSMISSION SELECTION LEVER (LOCATION UNK.)	BEYOND	CASE VEHICLE BOUNDARY
(59)	TRANSMISSION LEVER ON STEERING COLUMN		AREA EXTERIOR TO CAR (SPECIFIC AREA UNK.)
(44)	TRANSMISSION LEVER ON FLOOR OR CONSOLE	(70)	HOOD OF OTHER VEHICLE
(07)		(71)	OTHER VEHICLE EXTERIOR HARDWARE (E.G.
(84)	PARKING BRAKE HANDLE IN FRONT	(, ,)	OUTSIDE MIRRORS, ANTENNA, TRIM)
(85)	PARKING BRAKE HANDLE ON FLOOR OR CONSOLE	(73)	EXTERIOR SIDE ROOF RAIL OF OTHER VEHICLE
(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)	(74)	HEADLIGHT OR FRONT GRILL OF OTHER VEH.
	•	(75)	TRUNK OF OTHER VEHICLE
(29)	FRONT SEAT-BACK(S)	(76)	OUTSIDE SURFACE OF OTHER VEHICLE
(51)	FRONT SEAT CUSHION	(77)	TIRES OF OTHER VEHICLE
(50)	REAR SEAT CUSHION & BACK	(78)	GROUND
(49)	ARMREST ON SEAT	(79)	WATER
(89)	UNDER SEAT BOTTOM	(80)	EXTERIOR OBJECT (NOT VEHICLE, GROUND,
		(/	OR WATER. PLEASE DESCRIBE.)
(33)	RESTRAINT SYSTEM HARDWARE		
(34)	RESTRAINT SYSTEM WEBBING	PENETRA	ATING OBJECTS
(87)	AIR CUSHION SKIN (AIRBAG)		OTHER VEHICLE
(47)	AIRBAG (ACRS) COMPARTMENT DOOR/COVER	• •	OBJECTS (DESCRIBE)
(46)	AIRBAG GAS	\·-)	
(48)	KNEE RESTRAINT	MISCELL	ANEOUS
( <b>30</b> )	HEAD RESTRAINT		NO CONTACT (INVALID FIELD FORM CODE)
(42)	CHILD SEAT RESTRAINTS	(38)	
(43)	CHILD SEAT	· •	SPARE TIRE
(31)	INTERIOR LOOSE OBJECT	(96)	INDUCED
(32)	OTHER OCCUPANT(S)	(97)	EJECTED, UNKNOWN CONTACT
(52)	INTERNAL FLYING GLASS (FROM ANY SOURCE)	(98)	IMPACT FORCE, "WHIPLASH",
(41)	UNKNOWN INTERIOR SURFACE	, ,	HYPEREXTENSION/COMPRESSION
		(99)	UNKNOWN AREA OF CONTACT
		(33)	S. W. S.



#### CODES FOR OCCUPANT INJURY CLASSIFICATION (OIC)

#### 1 BODY REGION

- (H) HEAD/SKULL
- (F) FACE
- (N) NECK
- (S) SHOULDER
- (X) UPPER EXTREMITIES
- (A) ARM (UPPER)
- (E) ELBOW
- (R) FOREARM
- (W) WRIST/HAND
- (C) CHEST
- (M) ABDOMEN
- (B) BACK
- (P) PELVIC/HIP
- (Y) LOWER EXTREMITIES
- (T) THIGH
- (K) KNEE
- (L) LEG (LOWER)
- (Q) ANKLE/FOOT
- (O) WHOLE BODY
- (U) UNKNOWN

#### 3 LESION

- (L) LACERATION
- (C) CONTUSION
- (A) ABRASION
- (F) FRACTURE
- (P) PERFORATION, PUNCTURE
- (K) CONCUSSION
- (V) AVULSION
- (R) RUPTURE
- (S) SPRAIN
- (D) DISLOCATION
- (N) CRUSH
- (M) AMPUTATION
- (B) BURN
- (G) DETACHMENT, SEPARATION
- (Z) FRACTURE AND DISLOCATION
- (T) STRAIN
- (E) TOTAL SEVERANCE, TRANSECTION
- (O) OTHER
- (U) UNKNOWN

#### 4 SYSTEM/ORGAN

- (S) SKELETAL
- (V) VERTEBRAE
- (J) JOINTS
- (D) DIGESTIVE
- (L) LIVER
- (N) NERVOUS SYSTEM
- (B) BRAIN
- (C) SPINAL CORD
- (E) EARS
- (O) EYES
- (A) ARTERIES
- (H) HEART
- (Q) SPLEEN
- (G) UROGENITAL
- (K) KIDNEYS
- (R) RESPIRATORY
- (P) PULMONARY/LUNGS
- (M) MUSCLES
- (T) THYROID, OTHER ENDOCRINE GLAND
- (I) INTEGUMENTARY (SKIN)
- (W) ALL SYSTEMS IN REGION
- (U) UNKNOWN

#### 2 ASPECT

- (R) RIGHT
- (L) LEFT
- (B) BILATERAL
- (C) CENTRAL
- (A) ANTERIOR/FRONT
- (P) POSTERIOR/BACK
- (S) SUPERIOR/UPPER
- (I) INFERIOR/LOWER
- (W) WHOLE REGION
- (U) UNKNOWN

# SEVERITY 5 SYSTEM/ORGAN 4 LESION 9 ASPECT 0 BODY REGION 1

#### 5 SEVERITY (OR "AIS", ABBREVIATED INJURY SCALE)

- (0) NONE
- (1) MINOR
- (2) MODERATE
- (3) SERIOUS
- (4) SEVERE
- (5) CRITICAL
- (6) MAXIMUM
- (9) UNKNOWN







t Availabl





7----





PN 20400#



















































0400#3

















## CASENO 20400 CASEVORCE 1999

SEVENCE: 1996 Moreovy STATURE: 1

OCCUPANT (Breet) Myser old mate STATURE 185 ends 9, Fire MASS 96 kg (2 MESTAARTS 3,000 Det ggreen, setting fishers



## PN 20400 #41